




# Product Change Notification (PCN)

PCN Number	503442	Date Issued	December 01, 2017
Reason for Change	Capacity change or tool replacement		
Change Type Description	This letter is to inform you that another set of tooling is being added to meet the current and future demands of this product. There will be no changes in the fit, form or function from the additional tooling when compared to the current tooling.		
Reason for Short Notice	New Capacity		
Assessment of Change	Dimension analysis		
Internal Molex Qualification Date	January 02, 2018		
Sample Availability Date (Changed Part)	January 02, 2018		
Planned Implementation Date	January 02, 2018		
Method of Identifying Change	Product made after planned implementation date can contain the change		

RELEASED

## Before Change

- Affected part for the PCN- **3901-2061**  
**3901-2066**



## After Change

### Overview

- Molex is going to add a new set of tooling to meet the current and future demands of this product.
  - There will be no changes in the fit, form or function from the additional tooling when compared to the current tooling
- Product Impact
  - No impact to fit, form or function
- Part Number Impact
  - 3901-2061
  - 3901-2066
- Qualification Reports and samples available upon request after January 2, 2018

1 Molex Confidential Information  
© 2018 Molex - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.



2 Molex Confidential Information  
© 2018 Molex - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.





## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:503442**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

Molex Part #

39012061

469930610

Part Numbers Affected:

39-01-2061

39-01-2066