



PCN Tracking Number: PCN_FT_028

Issue Date: 2018-04-03

Product Change Notification

Product Part Number	FT4222HQ Hi-Speed Quad SPI/I²C device	Estimated implementation date
Description of Change	Update from Rev. C to Rev. D, to improve speed and minor bug fixes	April 2018
Reason for Change	Fix existing issues and improve GPIO performance.	
Detailed Description	All issues listed below have been fixed: 1. Data path is not fully reset when a reset on I²C is executed. 2. Not responding with a STALL to a get BOS descriptor as defined in USB3.0 Performance improvements: 1. Buffer size for data stream is changed in CNFMode1 and CNFMode2 2. Improved the detectable frequency on GPIOs	
Impact to Data sheet	Functions no change. Ordering information updated for FT4222HQ-D	
Benefit of Change	Issue fixes and performance improvement	
Markings to distinguish revised from:	Device date code will be changed to a "D" to indicate revision D	
Sample Availability	April 2018	
Risk Assessment, Fit Form and Function & reliability	Fit: Dimensions have not changed. Form : Visual appearance is unchanged except for markings for rev D Function: Device function remains unchanged, performance should be better	
PDF Download	http://www.ftdichip.com/Support/Documents/ProductChangeNotifications/PCN_FT_028.pdf	
Others:	For further details, please refer the Technical notes: http://www.ftdichip.com/Support/Documents/TechnicalNotes/TN_161_FT4222H%20Errata%20Technical%20Note.pdf http://www.ftdichip.com/Support/Documents/TechnicalNotes/TN_175_FT4222H%Rev.D%Technical%Note.pdf	