



PRODUCT OBSOLESCENCE MEMO

POSITION SENSORS



Certain Bourns® Multiturn Non-Contacting Magnetic Position Sensors with Less than 10 Turns and $\pm 0.3\%$ Linearity to be Discontinued

Bourns® AMM20B5A1C Models

Riverside, California – October 10, 2022 – In accordance with our ongoing product life cycle management procedure, Bourns is transferring certain [AMM20B](#) models to an End of Product Life status effective immediately. This action is necessary because an independent linearity tolerance of $\pm 0.3\%$ is too tight for models with an effective electrical angle less than 10 turns.

A list of affected part numbers is provided below.

| Affected Part Numbers | | |
|-----------------------|-------------------|-------------------|
| AMM20B5A1CLASL140 | AMM20B5A1CLASL324 | AMM20B5A1CLASL340 |

Bourns will not offer a direct replacement at this time; however, we do offer this linearity option for configurations in 10 to 16 turns for this series.

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

SC2217