P.IVA – VAT IT 00325250512 Cap. Soc. € 763.439 i.v. Reg. Imprese n. 4196 Arezzo REA n. 70645 Meccanografico AR007079

# PRODUCT CHANGE NOTIFICATION

Subject: Product Change Notification - PCN20210019

#### Type of Change:

Product [X] Process [] EOL [] General [] ECN[]

### Involved product (s):

RB69

## Change description:

The KINGSTONE eMMC P/N EMMC32G-TA29-PZ90 has been replaced with KINGSTONE P/N EMMC32G-TX29-8AC01. Due to the eMMC change, the part number change as follows

Old P/N	New P/N
RB69-17 <b>4</b> 0-2211-C2	RB69-17 <b>6</b> 0-2211-C2
RB69-28 <b>4</b> 0-2211-C2	RB69-28 <b>6</b> 0-2211-C2
RB69-77 <b>4</b> 0-2211-C2	RB69-77 <b>6</b> 0-2211-C2
RB69-88 <b>4</b> 0-2211-C2	RB69-88 <b>6</b> 0-2211-C2

In any case the eMMC option RB69-XX4X-XXXX-C2 has been replaced by the new eMMC option RB69-XX6X-XXXX-C2

The KINGSTONE eMMC P/N EMMC32G-IB29-PZ90 has been replaced with KINGSTONE P/N EMMC32G-IX29-8AC01. Due to the eMMC change, the part number change as follows

Old P/N	New P/N
RB69-67 <b>4</b> 0-2211-I2	RB69-67 <b>6</b> 0-2211-l2
RB69-77 <b>4</b> 0-2211-l2	RB69-77 <b>6</b> 0-2211-I2
RB69-88 <b>4</b> 0-2211-I2	RB69-88 <b>6</b> 0-2211-I2

In any case the eMMC option RB69-XX4X-XXXX-I2 has been replaced by the new eMMC option RB69-XX6X-XXXX-I2

The KINGSTONE eMMC P/N EMMC64G-TA29-PZ90 has been replaced with KINGSTONE P/N EMMC64G-TX29-8AC01. The eMMC option RB69-XX5X-XXXX-C2 has been replaced by the new eMMC option RB69-XX7X-XXXX-C2

The KINGSTONE eMMC P/N EMMC64G-IB29-PZ90 has been replaced with KINGSTONE P/N EMMC64G-IX29-8AC01. Due to the eMMC change, the part number change as follows

Old P/N	New P/N
RB69-67 <b>5</b> 0-2111-I2	RB69-67 <b>7</b> 0-2111-l2

The eMMC option RB69-XX5X-XXXX-I2 has been replaced by the new eMMC option RB69-XX7X-XXXX-I2

WWW.SECO.COM





P.IVA - VAT IT 00325250512 Cap. Soc. € 763.439 i.v. Reg. Imprese n. 4196 Arezzo REA n. 70645 Meccanografico AR007079

## Reason for Change:

EOL KINGSTONE eMMC EMMC64G-IB29-PZ90, EMMC64G-TA29-PZ90, EMMC32G-IB29-PZ90, EMMC32G-TA29-PZ90

## **Customer Impact of Change and Recommended Action:**

It is recommended to check the actual programming of your software. Please contact our commercilae for any request

## Associated schedule:

Once the stocks of the old eMMC are exhausted, we will move on to the new boards codes

## Reference documents:

PCN: PCN201022-01 PCN: PCN201218-01

Please do not hesitate to contact us for any questions or concerns.

Best Regards, SECO S.p.a. 24/05/2021



MILAN









