

Part Change Notice

JAE has modified the shape of the insulator of HB01 Series' pin connector. The modification was made to enhance the seating of the signal pin contact. Though a slight appearance change can be noticed to the pin contact insulator, the modification will not affect the performance nor mateability with the existing socket housing.


1. Applicable Product:

Part number: HB01P006PZ1

Drawing number: SJ116693

2. Change:

Changes made to the insulator material can be found in the diagram below.



3. Updated Schedule:

A running change started with products shipped on July 1, 2019.

4. Other Information:

There is no change for specification or performance. There is no change in mating condition with the existing socket insulator.

If you have any questions regarding this matter, please contact your JAE account manager.

Thank you for your cooperation.

