

PRODUCT CHANGE NOTIFICATION

Product Category REELSMART 20210520-1

Product Group TIES AND TERMINALS

ISSUE DATE: 11-Jan-21

IMPACTED REGIONS: NA EMEA LATAM AP


REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

A change has been made to the upper crimp die of CD-800-3 (orderable component: TD13475C06) that is used with the CA-800EZ ReelSmart applicator. The side walls of the crimp die have been shortened by 0.05 inches to optimize the crimp performance. This change will not affect the product's compliance to industry standards.

Please reach out to your local sales representative for a possible free replacement option; which is also still available for a similar change on the CD9-3B (TD24131C01).

Photos/Drawing (where applicable)



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2021	6	14
Old product discontinuation date*			

IMPACTED PART NUMBER(s)

TD13475C06
 CD-800-3
 CD-800-18