

# PRODUCT CHANGE NOTIFICATION (PCN)

Product Category FIBER PATCHCORDS 20210312-1

Product Group CONNECTIVITY & PATHWAYS

ISSUE DATE: 20210312

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

Discontinuation of some Fiber Patchcords.

**IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)**

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2021	3	12
Old product discontinuation date*	2021	6	1

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

Impacted Part Numbers	Replacement Part 1
F82ELANLNSNM023	NO-REPLACEMENT
F82ELANLNSNM041	NO-REPLACEMENT
F82RLUNUNSNM002	F92RLU1U1ONM002
F82RLUNUNSNM003	F92RLU1U1ONM003
FXBSCSCE2LM002	FX23LSNSNSNM002
FXBSCSCE2LM003	FX23LSNSNSNM003
FXQSCLCE2RM005	FX2ERLNSNSNM005
FZBSCSCLCE2RM005	FZ2ERLNSNSNM005
FZQSCLCE2RM005	FZ2ELLNSNONM005