

## Global Change Notification (GCN)

Product Family	M12 shielded cordsets (13 WE, 13 WL, 13 WO)	10648763
		GCN Number
Series	various	August 26, 2014
		Date Issued
Reason For Change	Change Construction Or Material	
Change Description	The purpose of this letter is to inform you of the implementation of an anti-vibration feature into the locking nut of the M12 male shielded cordset heads. This feature has already been implemented to a lot of our products and works without problems.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Special Request	
Assessment Of Change (How Product Will Be Qualified & Validated)	Qualification and validation of the new product will be according to the previous.	
Internal Molex Qualification Date (Planned Date Information Available)	October 08, 2014	
Sample Availability Date (Changed Part)	October 08, 2014	
Date of Implementation	October 15, 2014	
Method of Identifying Change	While turning the coupling nut, a slight rattling sound and small vibrations are perceivable	
Recommended Replacement Parts		
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)