



Product Change Notification

TE Connectivity

Product Change Notification: E-19-009235

PCN Date: 09-SEP-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Large heat shrink Identification sleeves, 25mm and above (1 inch and above).

Description of Changes
Relocation of manufacture to Europe. There is no change to fit, form or function.

Reason for Changes:
Manufacturing / Process Requirements. The existing site where these parts are made has been sold. Therefore these parts have to be relocated. A review of manufacturing footprint has prompted the relocation to an alternative TE manufacturing site in Trutnov, Cz.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	07-FEB-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
191509-000	NO			"8-1191388-9", "TMS-SCE-2-1/4-2.0-9"			
4397130001	NO			"3-1193304-2", "TMS-SCE-1-2.0-9"			
4602050003	NO			"9-1193451-3", "RPS-1-400/2.0-9"			
577739-000	NO			"5-1194582-9", "TMS-SCE-2-2.0-9"			
7992730001	NO			"6-1196179-1", "TMS-SCE-1-2.0-4"			
9410990001	NO			"9-1197286-5", "HT-SCE-3/4-2.0-9"			
996870-000	NO			"1-1197942-5", "TTMS-25.4-9"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4397130001	NO			"3-1193304-2", "TMS-SCE-1-2.0-9"			
7992730001	NO			"6-1196179-1", "TMS-SCE-1-2.0-4"			
9410990001	NO			"9-1197286-5", "HT-SCE-3/4-2.0-9"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
9410990001	NO			"9-1197286-5", "HT-SCE-3/4-2.0-9"			
996870-000	NO			"1-1197942-5", "TTMS-25.4-9"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4397130001	NO			"3-1193304-2", "TMS-SCE-1-2.0-9"			
9410990001	NO			"9-1197286-5", "HT-SCE-3/4-2.0-9"			
996870-000	NO			"1-1197942-5", "TTMS-25.4-9"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4602050003	NO			"9-1193451-3", "RPS-1-400/2.0-9"			
9410990001	NO			"9-1197286-5", "HT-SCE-3/4-2.0-9"			
996870-000	NO			"1-1197942-5", "TTMS-25.4-9"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
191509-000	NO			"8-1191388-9", "TMS-SCE-2-1/4-2.0-9"			
4602050003	NO			"9-1193451-3", "RPS-1-400/2.0-9"			
577739-000	NO			"5-1194582-9", "TMS-SCE-2-2.0-9"			
9410990001	NO			"9-1197286-5", "HT-SCE-3/4-2.0-9"			
996870-000	NO			"1-1197942-5", "TTMS-25.4-9"			