



Product Change Notification (PCN)


PCN Number	511152	Date Issued	November 05, 2021
Reason for Change	Capacity change or tool replacement		
Change Type Description	This letter is to inform you that another set of tooling is being added to meet the current and future demands of this product. There will be no changes in the fit, form or function from the additional tooling when compared to the current tooling.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	First article inspection		
Internal Molex Qualification Date	November 10, 2021		
Sample Availability Date (Changed Part)	November 10, 2021		
Planned Implementation Date	December 05, 2021		
Method of Identifying Change	Lot information on label		

RELEASED

Before Change

After Change

Mold refurbishment for 540170615 and 540180605



- Restore productivity by refurbishing mold for 540170615 and 540180605.
 - The parting line and gate position on the product surface will be changed as attached picture.
 - The mold number marking will be changed from A to B.
- Product Impact
 - The parting line and gate position on the product surface will be changed. But there are no impact to fit, or function
- Part Number Impact
 - see attached impacted parts list
- How the change implement
 - Running change
- This product is manufactured at Japan supplier and this change will only impact Molex Japan supplier.
- Qualification Reports and samples available upon request after the date shown above



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:511152**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

PCN # Molex Part #

511152 540170615

511152 540180605