

# PRODUCT CHANGE NOTIFICATION

Product Category FIBER PATCHCORDS 20230201-1

Product Group CONNECTIVITY & PATHWAYS

ISSUE DATE: 1-Feb-23

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

Discontinuation of some Fiber Patchcord products. Thanks for your ongoing support. Please review the product notification for a list of the affected parts.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2023	5	2

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

**IMPACTED PART NUMBER(s) Replacement Part 1**

PVQ9LE03LQM01.5	NO-REPLACEMENT
PVQ9LE03LQM02.0	NO-REPLACEMENT
PVQ9LE03LQM03.0	NO-REPLACEMENT
PVQ9LE03LQM05.0	NO-REPLACEMENT
PVQ9LE03LQM10.0	NO-REPLACEMENT
PVQ9LE03LQM20.0	NO-REPLACEMENT
PVQ9LE10LQM00.5	NO-REPLACEMENT
PVQ9LE10LQM01.0	NO-REPLACEMENT
PVQ9LE10LQM01.5	NO-REPLACEMENT
PVQ9LE10LQM02.0	NO-REPLACEMENT
PVQ9LE10LQM02.5	NO-REPLACEMENT
PVQ9LE10LQM03.0	NO-REPLACEMENT
PVQ9LE10LQM03.5	NO-REPLACEMENT
PVQ9LE10LQM04.5	NO-REPLACEMENT
PVQ9LE10LQM05.0	NO-REPLACEMENT
PVQ9LE10LQM06.0	NO-REPLACEMENT
PVQ9LE10LQM06.5	NO-REPLACEMENT
PVQ9LE10LQM07.0	NO-REPLACEMENT
PVQ9LE10LQM07.5	NO-REPLACEMENT
PVQ9LE10LQM08.0	NO-REPLACEMENT
PVQ9LE10LQM08.5	NO-REPLACEMENT
PVQ9LE10LQM09.0	NO-REPLACEMENT
PVQ9LE10LQM10.0	NO-REPLACEMENT
PVQ9LE10LQM12.0	NO-REPLACEMENT
PVQ9LE10LQM20.0	NO-REPLACEMENT
PVQ9LE10LQM25.0	NO-REPLACEMENT
PVQ9LE10LQM50.0	NO-REPLACEMENT
PVQ9PE10LQM00.5	NO-REPLACEMENT
PVQ9PE10LQM01.5	NO-REPLACEMENT
PVQ9PE10LQM02.0	NO-REPLACEMENT
PVQ9PE10LQM03.0	NO-REPLACEMENT
PVQ9PE10LQM03.5	NO-REPLACEMENT
PVQ9PE10LQM04.5	NO-REPLACEMENT
PVQ9PE10LQM05.0	NO-REPLACEMENT
PVQ9PE10LQM06.0	NO-REPLACEMENT
PVQ9PE10LQM06.5	NO-REPLACEMENT
PVQ9PE10LQM07.5	NO-REPLACEMENT
PVQ9PE10LQM08.0	NO-REPLACEMENT
PVQ9PE10LQM09.0	NO-REPLACEMENT
PVQ9PE10LQM09.5	NO-REPLACEMENT
PVQXLE03LQM02.0	NO-REPLACEMENT
PVQXLE03LQM03.0	NO-REPLACEMENT
PVQXLE10LQM00.5	NO-REPLACEMENT
PVQXLE10LQM01.0	NO-REPLACEMENT
PVQXLE10LQM02.0	NO-REPLACEMENT

PVQXLE10LQM02.5	NO-REPLACEMENT
PVQXLE10LQM03.5	NO-REPLACEMENT
PVQXLE10LQM04.0	NO-REPLACEMENT
PVQXLE10LQM05.0	NO-REPLACEMENT
PVQXLE10LQM05.5	NO-REPLACEMENT
PVQXLE10LQM06.5	NO-REPLACEMENT
PVQXLE10LQM07.0	NO-REPLACEMENT
PVQXLE10LQM08.0	NO-REPLACEMENT
PVQXLE10LQM08.5	NO-REPLACEMENT
PVQXLE10LQM09.5	NO-REPLACEMENT
PVQXLE10LQM10.0	NO-REPLACEMENT
PVQXPE10LQM00.5	NO-REPLACEMENT
PVQXPE10LQM01.0	NO-REPLACEMENT
PVQXPE10LQM02.0	NO-REPLACEMENT
PVQXPE10LQM02.5	NO-REPLACEMENT
PVQXPE10LQM03.5	NO-REPLACEMENT
PVQXPE10LQM04.0	NO-REPLACEMENT
PVQXPE10LQM05.0	NO-REPLACEMENT
PVQXPE10LQM05.5	NO-REPLACEMENT
PVQXPE10LQM06.0	NO-REPLACEMENT
PVQXPE10LQM06.5	NO-REPLACEMENT
PVQXPE10LQM07.0	NO-REPLACEMENT
PVQXPE10LQM07.5	NO-REPLACEMENT
PVQXPE10LQM08.0	NO-REPLACEMENT
PVQXPE10LQM08.5	NO-REPLACEMENT
PVQXPE10LQM09.0	NO-REPLACEMENT
PVQXPE10LQM09.5	NO-REPLACEMENT
PVQXPE10LQM10.0	NO-REPLACEMENT
PVQXPE10LQM12.0	NO-REPLACEMENT
PVQXPE10LQM20.0	NO-REPLACEMENT
PVQZLE03LQM01.5	NO-REPLACEMENT
PVQZLE03LQM03.0	NO-REPLACEMENT
PVQZLE03LQM05.0	NO-REPLACEMENT
PVQZLE03LQM10.0	NO-REPLACEMENT
PVQZLE03LQM15.0	NO-REPLACEMENT
PVQZLE10LQM00.5	NO-REPLACEMENT
PVQZLE10LQM01.0	NO-REPLACEMENT
PVQZLE10LQM02.0	NO-REPLACEMENT
PVQZLE10LQM02.5	NO-REPLACEMENT
PVQZLE10LQM03.5	NO-REPLACEMENT
PVQZLE10LQM04.0	NO-REPLACEMENT
PVQZLE10LQM04.5	NO-REPLACEMENT
PVQZLE10LQM05.0	NO-REPLACEMENT
PVQZLE10LQM05.5	NO-REPLACEMENT
PVQZLE10LQM06.0	NO-REPLACEMENT
PVQZLE10LQM06.5	NO-REPLACEMENT
PVQZLE10LQM07.0	NO-REPLACEMENT
PVQZLE10LQM07.5	NO-REPLACEMENT

PVQZLE10LQM08.0	NO-REPLACEMENT
PVQZLE10LQM08.5	NO-REPLACEMENT
PVQZLE10LQM09.0	NO-REPLACEMENT
PVQZLE10LQM09.5	NO-REPLACEMENT
PVQZLE10LQM15.0	NO-REPLACEMENT
PVQZLE10LQM20.0	NO-REPLACEMENT
PVQZLE10LQM50.0	NO-REPLACEMENT
PVQZPE10LQM00.5	NO-REPLACEMENT
PVQZPE10LQM01.5	NO-REPLACEMENT
PVQZPE10LQM02.0	NO-REPLACEMENT
PVQZPE10LQM03.0	NO-REPLACEMENT
PVQZPE10LQM03.5	NO-REPLACEMENT
PVQZPE10LQM04.5	NO-REPLACEMENT
PVQZPE10LQM05.0	NO-REPLACEMENT
PVQZPE10LQM06.0	NO-REPLACEMENT
PVQZPE10LQM06.5	NO-REPLACEMENT
PVQZPE10LQM07.5	NO-REPLACEMENT
PVQZPE10LQM08.0	NO-REPLACEMENT
PVQZPE10LQM09.0	NO-REPLACEMENT
PVQZPE10LQM09.5	NO-REPLACEMENT
PVQZPE10LQM15.0	NO-REPLACEMENT
PVQ9LE10LQM04.0	NO-REPLACEMENT
PVQ9LE10LQM05.5	NO-REPLACEMENT
PVQ9LE10LQM09.5	NO-REPLACEMENT
PVQ9LE10LQM15.0	NO-REPLACEMENT
PVQ9LE10LQM30.0	NO-REPLACEMENT
PVQ9PE10LQM01.0	NO-REPLACEMENT
PVQ9PE10LQM02.5	NO-REPLACEMENT
PVQ9PE10LQM04.0	NO-REPLACEMENT
PVQ9PE10LQM05.5	NO-REPLACEMENT
PVQ9PE10LQM07.0	NO-REPLACEMENT
PVQ9PE10LQM08.5	NO-REPLACEMENT
PVQ9PE10LQM10.0	NO-REPLACEMENT
PVQXLE03LQM05.0	NO-REPLACEMENT
PVQXLE10LQM01.5	NO-REPLACEMENT
PVQXLE10LQM03.0	NO-REPLACEMENT
PVQXLE10LQM04.5	NO-REPLACEMENT
PVQXLE10LQM06.0	NO-REPLACEMENT
PVQXLE10LQM07.5	NO-REPLACEMENT
PVQXLE10LQM09.0	NO-REPLACEMENT
PVQXLE10LQM15.0	NO-REPLACEMENT
PVQXPE10LQM01.5	NO-REPLACEMENT
PVQXPE10LQM03.0	NO-REPLACEMENT
PVQXPE10LQM04.5	NO-REPLACEMENT
PVQXPE10LQM18.0	NO-REPLACEMENT
PVQZLE03LQM02.0	NO-REPLACEMENT
PVQZLE03LQM07.0	NO-REPLACEMENT
PVQZLE03LQM20.0	NO-REPLACEMENT

PVQZLE10LQM01.5	NO-REPLACEMENT
PVQZLE10LQM03.0	NO-REPLACEMENT
PVQZLE10LQM10.0	NO-REPLACEMENT
PVQZLE10LQM25.0	NO-REPLACEMENT
PVQZPE10LQM01.0	NO-REPLACEMENT
PVQZPE10LQM02.5	NO-REPLACEMENT
PVQZPE10LQM04.0	NO-REPLACEMENT
PVQZPE10LQM05.5	NO-REPLACEMENT
PVQZPE10LQM07.0	NO-REPLACEMENT
PVQZPE10LQM08.5	NO-REPLACEMENT
PVQZPE10LQM10.0	NO-REPLACEMENT