



22nd January 2013

To Our Valued Customers:

Subject: 3M™ Water Contact Indicator Tape 5557NP Discontinuation

This letter is to notify you that, 3M™ Water Contact Indicator Tape 5557NP will be discontinued with effective 1st January 2013.

3M™ Ultra-Thin Water Contact Indicator Tape 5558 is the recommended replacement. This product has an added feature of printable top film.

For any technical questions regarding 3M™ Ultra-Thin Water Contact Indicator Tape 5558, please kindly contact your local 3M Technical Service Representative.

Thank you for your continued support of 3M.