

# Product Discontinuation



## PD\_092\_16

■ Last Order Date:	2017-03-30
■ Last Delivery Date:	2017-09-30

Reason: Discontinuation of specific products in PG-TSSOP-16 package

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
TDA5100	SP000016393	TDA5100XUMA1	PG-TSSOP-16-1			none	
TDA5101	SP000012901	TDA5101XUMA3	PG-TSSOP-16-1			none	
TDA5101	SP000016386	TDA5101XUMA1	PG-TSSOP-16-1			none	
TDA5101	SP000016388	TDA5101XUMA2	PG-TSSOP-16-1			none	
TDA5102	SP000013431		PG-TSSOP-16-1			none	
TDA5102	SP000013432	TDA5102XUMA1	PG-TSSOP-16-1			none	
TDA7110	SP000524278	TDA7110XUMA1	PG-TSSOP-16-1			none	
TDK5100	SP000014557	TDK5100XUMA1	PG-TSSOP-16-1			none	
TDK5101	SP000014559	TDK5101XUMA1	PG-TSSOP-16-1			none	
TDK5110	SP000013532	TDK5110XUMA1	PG-TSSOP-16-1			none	
TDK5111	SP000014017	TDK5111XUMA1	PG-TSSOP-16-1			none	

If you have any questions, please do not hesitate to contact your local sales office.

**Disclaimer:** The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!