

<b>Product Name:</b>	HPL 676 - Flex Lock	
	FlexLock Header	
<b>Product Manager:</b>	Jennifer Zhang	
<b>Subject:</b>	Notification of Change with Immediate Effectivity	
<b>Distribution:</b>	Affected customers	
<b>Type of Change:</b>	Packaging Change	
<b>Change Description:</b>	Change of carrier tape material from Polystyrene Black to Transparent Polystyrene.	
<b>Reason for Change:</b>	As part of improvement. Using the existing carrier tape made by Polystyrene Black, the Operator can't check the pin status after packaging. After changing to Transparent Polystyrene, operator can find the pin deformation, missing pin etc. after packaging.	
<b>Affected Parts:</b>	See Affected parts.xls	
<b>Effective Date of Change:</b>	January,31 2023	
<b>Last Time Buy Date:</b>		
<b>Earliest Disty Return Date:</b>		
<b>Last Time Shipment Date</b>		
<b>Datasheet Attached?</b>		
<b>Qual/Test Data Attached?</b>		
<b>Samples Availability Date:</b>	01 January ,2023	
<b>Available Alternatives?</b>		
<b>Questions?</b>	<i>Contact your local ACS Representative, or Product Manager</i>	
	<i>Jennifer Zhang</i>	
	<i>Jennifer.Zhang@fci.com</i>	

**Note:**

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

**MPN**

10158557-R122121LF

10158557-R281111LF

10158557-R282111LF

10158557-R301111LF

10158557-R302111LF

10164521-R181000LF

10165157-R041000LF

10166409-F20210ALF

10166409-F20210BLF

10166409-F24210ALF

10166409-F24210BLF

10166409-F32210ALF

10166409-F32210BLF

10166409-F32210CLF

10166409-F36210ALF

10158557-R122111LF

10158557-R122221LF

10158557-R301211LF