



# Product Change Notification

## TE Connectivity

Product Change Notification: P-18-016641

PCN Date: 27-NOV-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

Manufacturing Location Change of Menlo Park Appliances Tubing RNF-100 Products

**Description of Changes**

Manufacturing location change. Back in 2016 (see PCN P-16-013872) TE connectivity notified that we have qualified RNF-100 for Manufacture in the Trutnov plant and would start the manufacturing transfer process. Since this time, we have learned many lessons and faced many challenges in this complex transfer. Consequently, we need to process future product transfers within this project a little differently. To do this we will be issuing new part numbers to all the transferring products which have the Unit of measure of Feet. Future Units of Measure will be either Piece or Metres. We will retrospectively issue new part numbers for the RNF-100 parts that have already moved for manufacture in the Trutnov plant. As part of the production move, we will start to ship additional RNF-100 tubing products after 28th February 2019 from the Trutnov facility. After this date TE reserves the right to provide qualified products from Menlo or Trutnov manufacturing locations.

**Other attachments:**

- [PCN RNF-100 Notification](#)
- [PCN RNF-100 Part Numbers](#)
- [PCN RNF-100 Notification](#)
- [PCN RNF-100 Part Numbers](#)
- [PCN RNF-100 Notification](#)
- [PCN RNF-100 Part Numbers](#)

**Reason for Changes:**

Dear Customer, we hereby inform you about a transfer of processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. Upon request, a PPAP Level 2 will be available if it concerns a transfer of a tool which produces a finished TE-product. A PPAP Level 1 will be available if it concerns a component of a TE-product, where the production location of the finished TE-product remains unchanged. If you require such a PPAP, please notify the responsible TE Sales Contact within 14 calendar days after receipt of this PCN. TE will also be changing the Unit of measure for the -STK descriptions. The original UOM was either Feet for the new parts the UOM is Piece

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	28-FEB-2019
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	30-SEP-2019

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">003347-000</a>	NO			"3-1190025-7", "RNF-100-3/8-YO-FSP"			
<a href="#">071275-000</a>	NO			"3-1190535-5", "RNF-100-1/2-BK-FSP"			
<a href="#">142003-000</a>	NO			"1-1191029-3", "RNF-100-3/4-BK-FSP"			
<a href="#">152125-000</a>	NO			"5-1191099-6", "RNF-100-1-CL-FSP"			
<a href="#">292801-000</a>	NO			"5-1192219-1", "RNF-100-1-BK-FSP"			
<a href="#">314363-000</a>	NO			"5-1192379-2", "RNF-100-1/2-BU-FSP"			
<a href="#">408941-000</a>	NO			"5-1193084-6", "RNF-100-3/8-RD-FSP"			
<a href="#">411221-000</a>	NO			"3-1193101-5", "RNF-100-1/2-CL-FSP"			
<a href="#">446253-000</a>	NO			"1-1193354-2", "RNF-100-3/4-CL-FSP"			
<a href="#">467625-000</a>	NO			"1193505-8", "RNF-100-1-YO-FSP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5050154002</a>	NO			"1193815-7", "RNF-100-NO.302-BK-SP"			
<a href="#">5050964002</a>	NO			"9-1193817-4", "RNF-100-NO.301-BK-SP"			
<a href="#">5051514001</a>	NO			"3-1193819-9", "RNF-100-NO.300-BK-SP"			
<a href="#">5052842057</a>	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
<a href="#">5052892107</a>	NO			"5-1193823-3", "RNF-100-1/16-BK-STK"			
<a href="#">5052934106</a>	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
<a href="#">5052942218</a>	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
<a href="#">5052984151</a>	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
<a href="#">5052992172</a>	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			
<a href="#">5053024047</a>	NO			"8-1193836-7", "RNF-100-1/8-BU-SP", "RNF-100-1/8-6"			
<a href="#">5053034137</a>	NO			"5-1193837-2", "RNF-100-1/8-WH-SP"			
<a href="#">5053042176</a>	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
<a href="#">5053054039</a>	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
<a href="#">5053064084</a>	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
<a href="#">5053074047</a>	NO			"2-1193843-9", "RNF-100-3/16-BU-SP"			
<a href="#">5053084107</a>	NO			"9-1193843-5", "RNF-100-3/16-WH-SP"			
<a href="#">5053092267</a>	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
<a href="#">5053104060</a>	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
<a href="#">5053134121</a>	NO			"7-1193851-1", "RNF-100-1/4-WH-SP"			
<a href="#">5053142385</a>	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
<a href="#">5053192266</a>	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
<a href="#">5053194267</a>	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
<a href="#">5053232077</a>	NO			"1193868-6", "RNF-100-1/2-WH-STK"			
<a href="#">5053242179</a>	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
<a href="#">5053292160</a>	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
<a href="#">5053302039</a>	NO			"1193878-3", "RNF-100-1-RD-STK"			
<a href="#">5053342101</a>	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
<a href="#">5053344102</a>	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
<a href="#">5053392064</a>	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
<a href="#">5053394065</a>	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
<a href="#">5053442033</a>	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
<a href="#">5053444034</a>	NO			"6-1193887-4", "RNF-100-3-BK-SP"			
<a href="#">5053492029</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"1-1193889-0", "RNF-100-4-BK-STK"			
<a href="#">5053494030</a>	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
<a href="#">5054424024</a>	NO			"9-1193898-4", "RNF-100-1/8-GN-SP"			
<a href="#">5056844010</a>	NO			"9-1193902-5", "RNF-100-1-1/4-BK-SP"			
<a href="#">5070014034</a>	NO			"RNF-100-3/64-CL-SP", "1642707-1"			
<a href="#">5070024041</a>	NO			"3-1193959-4", "RNF-100-1/16-CL-SP"			
<a href="#">5070032071</a>	NO			"1193960-3", "RNF-100-3/32-CL-STK"			
<a href="#">5070034072</a>	NO			"1-1193960-3", "RNF-100-3/32-CL-SP"			
<a href="#">5070044083</a>	NO			"1193961-7", "RNF-100-1/8-CL-SP"			
<a href="#">5070054057</a>	NO			"RNF-100-3/16-CL-SP", "1832014-1"			
<a href="#">5070064069</a>	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
<a href="#">5070114069</a>	NO			"8-1193968-0", "RNF-100-1-1/2-CL-SP"			
<a href="#">540963-000</a>	NO			"7-1194242-7", "RNF-100-3/8-BK-FSP"			
<a href="#">769283-000</a>	NO			"4-1195994-9", "RNF-100-3/8-WH-FSP"			
<a href="#">9053854002</a>	NO			"2-1197035-2", "RNF-100-NO.301-CL-SP"			
<a href="#">911779-000</a>	NO			"2-1197081-1", "RNF-100-3/8-CL-FSP"			
<a href="#">969515-000</a>	NO			"4-1197495-3", "RNF-100-1-WH-FSP"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">071275-000</a>	NO			"3-1190535-5", "RNF-100-1/2-BK-FSP"			
<a href="#">142003-000</a>	NO			"1-1191029-3", "RNF-100-3/4-BK-FSP"			
<a href="#">152125-000</a>	NO			"5-1191099-6", "RNF-100-1-CL-FSP"			
<a href="#">292801-000</a>	NO			"5-1192219-1", "RNF-100-1-BK-FSP"			
<a href="#">408941-000</a>	NO			"5-1193084-6", "RNF-100-3/8-RD-FSP"			
<a href="#">446253-000</a>	NO			"1-1193354-2", "RNF-100-3/4-CL-FSP"			
<a href="#">5051514001</a>	NO			"3-1193819-9", "RNF-100-NO.300-BK-SP"			
<a href="#">5052842057</a>	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
<a href="#">5052892107</a>	NO			"5-1193823-3", "RNF-100-1/16-BK-STK"			
<a href="#">5052942218</a>	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
<a href="#">5052984151</a>	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
<a href="#">5052992172</a>	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5053024047</a>	NO			"8-1193836-7", "RNF-100-1/8-BU-SP", "RNF-100-1/8-6"			
<a href="#">5053042176</a>	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
<a href="#">5053074047</a>	NO			"2-1193843-9", "RNF-100-3/16-BU-SP"			
<a href="#">5053084107</a>	NO			"9-1193843-5", "RNF-100-3/16-WH-SP"			
<a href="#">5053092267</a>	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
<a href="#">5053134121</a>	NO			"7-1193851-1", "RNF-100-1/4-WH-SP"			
<a href="#">5053142385</a>	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
<a href="#">5053192266</a>	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
<a href="#">5053194267</a>	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
<a href="#">5053232077</a>	NO			"1193868-6", "RNF-100-1/2-WH-STK"			
<a href="#">5053242179</a>	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
<a href="#">5053292160</a>	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
<a href="#">5053302039</a>	NO			"1193878-3", "RNF-100-1-RD-STK"			
<a href="#">5053342101</a>	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
<a href="#">5053344102</a>	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
<a href="#">5053392064</a>	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
<a href="#">5053394065</a>	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
<a href="#">5053442033</a>	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
<a href="#">5053492029</a>	NO			"1-1193889-0", "RNF-100-4-BK-STK"			
<a href="#">5054424024</a>	NO			"9-1193898-4", "RNF-100-1/8-GN-SP"			
<a href="#">5056844010</a>	NO			"9-1193902-5", "RNF-100-1-1/4-BK-SP"			
<a href="#">5070014034</a>	NO			"RNF-100-3/64-CL-SP", "1642707-1"			
<a href="#">5070024041</a>	NO			"3-1193959-4", "RNF-100-1/16-CL-SP"			
<a href="#">5070032071</a>	NO			"1193960-3", "RNF-100-3/32-CL-STK"			
<a href="#">5070034072</a>	NO			"1-1193960-3", "RNF-100-3/32-CL-SP"			
<a href="#">5070044083</a>	NO			"1193961-7", "RNF-100-1/8-CL-SP"			
<a href="#">5070054057</a>	NO			"RNF-100-3/16-CL-SP", "1832014-1"			
<a href="#">5070064069</a>	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
<a href="#">5070114069</a>	NO			"8-1193968-0", "RNF-100-1-1/2-CL-SP"			
<a href="#">540963-000</a>	NO			"7-1194242-7", "RNF-100-3/8-BK-FSP"			
<a href="#">769283-000</a>	NO			"4-1195994-9", "RNF-100-3/8-WH-FSP"			
<a href="#">911779-000</a>	NO			"2-1197081-1", "RNF-100-3/8-CL-FSP"			

## Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">003347-000</a>	NO			"3-1190025-7", "RNF-100-3/8-YO-FSP"			
<a href="#">071275-000</a>	NO			"3-1190535-5", "RNF-100-1/2-BK-FSP"			
<a href="#">142003-000</a>	NO			"1-1191029-3", "RNF-100-3/4-BK-FSP"			
<a href="#">152125-000</a>	NO			"5-1191099-6", "RNF-100-1-CL-FSP"			
<a href="#">292801-000</a>	NO			"5-1192219-1", "RNF-100-1-BK-FSP"			
<a href="#">314363-000</a>	NO			"5-1192379-2", "RNF-100-1/2-BU-FSP"			
<a href="#">408941-000</a>	NO			"5-1193084-6", "RNF-100-3/8-RD-FSP"			
<a href="#">411221-000</a>	NO			"3-1193101-5", "RNF-100-1/2-CL-FSP"			
<a href="#">446253-000</a>	NO			"1-1193354-2", "RNF-100-3/4-CL-FSP"			
<a href="#">467625-000</a>	NO			"1193505-8", "RNF-100-1-YO-FSP"			
<a href="#">5050154002</a>	NO			"1193815-7", "RNF-100-NO.302-BK-SP"			
<a href="#">5051514001</a>	NO			"3-1193819-9", "RNF-100-NO.300-BK-SP"			
<a href="#">5052842057</a>	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
<a href="#">5052892107</a>	NO			"5-1193823-3", "RNF-100-1/16-BK-STK"			
<a href="#">5052934106</a>	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
<a href="#">5052942218</a>	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
<a href="#">5052984151</a>	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
<a href="#">5052992172</a>	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			
<a href="#">5053024047</a>	NO			"8-1193836-7", "RNF-100-1/8-BU-SP", "RNF-100-1/8-6"			
<a href="#">5053042176</a>	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
<a href="#">5053054039</a>	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
<a href="#">5053064084</a>	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
<a href="#">5053074047</a>	NO			"2-1193843-9", "RNF-100-3/16-BU-SP"			
<a href="#">5053084107</a>	NO			"9-1193843-5", "RNF-100-3/16-WH-SP"			
<a href="#">5053092267</a>	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
<a href="#">5053104060</a>	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
<a href="#">5053134121</a>	NO			"7-1193851-1", "RNF-100-1/4-WH-SP"			
<a href="#">5053142385</a>	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
<a href="#">5053192266</a>	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
<a href="#">5053232077</a>	NO			"1193868-6", "RNF-100-1/2-WH-STK"			
<a href="#">5053242179</a>	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
<a href="#">5053292160</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"3-1193876-7", "RNF-100-1-BK-STK"			
<a href="#">5053302039</a>	NO			"1193878-3", "RNF-100-1-RD-STK"			
<a href="#">5053344102</a>	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
<a href="#">5053392064</a>	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
<a href="#">5053394065</a>	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
<a href="#">5053442033</a>	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
<a href="#">5053444034</a>	NO			"6-1193887-4", "RNF-100-3-BK-SP"			
<a href="#">5053492029</a>	NO			"1-1193889-0", "RNF-100-4-BK-STK"			
<a href="#">5053494030</a>	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
<a href="#">5054424024</a>	NO			"9-1193898-4", "RNF-100-1/8-GN-SP"			
<a href="#">5056844010</a>	NO			"9-1193902-5", "RNF-100-1-1/4-BK-SP"			
<a href="#">5070014034</a>	NO			"RNF-100-3/64-CL-SP", "1642707-1"			
<a href="#">5070024041</a>	NO			"3-1193959-4", "RNF-100-1/16-CL-SP"			
<a href="#">5070032071</a>	NO			"1193960-3", "RNF-100-3/32-CL-STK"			
<a href="#">5070034072</a>	NO			"1-1193960-3", "RNF-100-3/32-CL-SP"			
<a href="#">5070044083</a>	NO			"1193961-7", "RNF-100-1/8-CL-SP"			
<a href="#">5070054057</a>	NO			"RNF-100-3/16-CL-SP", "1832014-1"			
<a href="#">5070064069</a>	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
<a href="#">5070114069</a>	NO			"8-1193968-0", "RNF-100-1-1/2-CL-SP"			
<a href="#">540963-000</a>	NO			"7-1194242-7", "RNF-100-3/8-BK-FSP"			
<a href="#">769283-000</a>	NO			"4-1195994-9", "RNF-100-3/8-WH-FSP"			
<a href="#">969515-000</a>	NO			"4-1197495-3", "RNF-100-1-WH-FSP"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">003347-000</a>	NO			"3-1190025-7", "RNF-100-3/8-YO-FSP"			
<a href="#">142003-000</a>	NO			"1-1191029-3", "RNF-100-3/4-BK-FSP"			
<a href="#">152125-000</a>	NO			"5-1191099-6", "RNF-100-1-CL-FSP"			
<a href="#">314363-000</a>	NO			"5-1192379-2", "RNF-100-1/2-BU-FSP"			
<a href="#">408941-000</a>	NO			"5-1193084-6", "RNF-100-3/8-RD-FSP"			
<a href="#">411221-000</a>	NO			"3-1193101-5", "RNF-100-1/2-CL-FSP"			
<a href="#">467625-000</a>	NO			"1193505-8", "RNF-100-1-YO-FSP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5050964002</a>	NO			"9-1193817-4", "RNF-100-NO.301-BK-SP"			
<a href="#">5051514001</a>	NO			"3-1193819-9", "RNF-100-NO.300-BK-SP"			
<a href="#">5052934106</a>	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
<a href="#">5052984151</a>	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
<a href="#">5053034137</a>	NO			"5-1193837-2", "RNF-100-1/8-WH-SP"			
<a href="#">5053054039</a>	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
<a href="#">5053064084</a>	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
<a href="#">5053074047</a>	NO			"2-1193843-9", "RNF-100-3/16-BU-SP"			
<a href="#">5053084107</a>	NO			"9-1193843-5", "RNF-100-3/16-WH-SP"			
<a href="#">5053104060</a>	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
<a href="#">5053134121</a>	NO			"7-1193851-1", "RNF-100-1/4-WH-SP"			
<a href="#">5053394065</a>	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
<a href="#">5053444034</a>	NO			"6-1193887-4", "RNF-100-3-BK-SP"			
<a href="#">5053494030</a>	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
<a href="#">5070024041</a>	NO			"3-1193959-4", "RNF-100-1/16-CL-SP"			
<a href="#">5070044083</a>	NO			"1193961-7", "RNF-100-1/8-CL-SP"			
<a href="#">5070054057</a>	NO			"RNF-100-3/16-CL-SP", "1832014-1"			
<a href="#">5070064069</a>	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
<a href="#">540963-000</a>	NO			"7-1194242-7", "RNF-100-3/8-BK-FSP"			
<a href="#">769283-000</a>	NO			"4-1195994-9", "RNF-100-3/8-WH-FSP"			
<a href="#">9053854002</a>	NO			"2-1197035-2", "RNF-100-NO.301-CL-SP"			
<a href="#">911779-000</a>	NO			"2-1197081-1", "RNF-100-3/8-CL-FSP"			
<a href="#">969515-000</a>	NO			"4-1197495-3", "RNF-100-1-WH-FSP"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">003347-000</a>	NO			"3-1190025-7", "RNF-100-3/8-YO-FSP"			
<a href="#">314363-000</a>	NO			"5-1192379-2", "RNF-100-1/2-BU-FSP"			
<a href="#">408941-000</a>	NO			"5-1193084-6", "RNF-100-3/8-RD-FSP"			
<a href="#">411221-000</a>	NO			"3-1193101-5", "RNF-100-1/2-CL-FSP"			
<a href="#">467625-000</a>	NO			"1193505-8", "RNF-100-1-YO-FSP"			
<a href="#">5050154002</a>	NO			"1193815-7", "RNF-100-NO.302-BK-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5051514001</a>	NO			"3-1193819-9", "RNF-100-NO.300-BK-SP"			
<a href="#">5052934106</a>	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
<a href="#">5052984151</a>	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
<a href="#">5053054039</a>	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
<a href="#">5053064084</a>	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
<a href="#">5053074047</a>	NO			"2-1193843-9", "RNF-100-3/16-BU-SP"			
<a href="#">5053104060</a>	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
<a href="#">5053134121</a>	NO			"7-1193851-1", "RNF-100-1/4-WH-SP"			
<a href="#">5053444034</a>	NO			"6-1193887-4", "RNF-100-3-BK-SP"			
<a href="#">5053494030</a>	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
<a href="#">769283-000</a>	NO			"4-1195994-9", "RNF-100-3/8-WH-FSP"			
<a href="#">969515-000</a>	NO			"4-1197495-3", "RNF-100-1-WH-FSP"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">003347-000</a>	NO			"3-1190025-7", "RNF-100-3/8-YO-FSP"			
<a href="#">142003-000</a>	NO			"1-1191029-3", "RNF-100-3/4-BK-FSP"			
<a href="#">152125-000</a>	NO			"5-1191099-6", "RNF-100-1-CL-FSP"			
<a href="#">314363-000</a>	NO			"5-1192379-2", "RNF-100-1/2-BU-FSP"			
<a href="#">408941-000</a>	NO			"5-1193084-6", "RNF-100-3/8-RD-FSP"			
<a href="#">411221-000</a>	NO			"3-1193101-5", "RNF-100-1/2-CL-FSP"			
<a href="#">467625-000</a>	NO			"1193505-8", "RNF-100-1-YO-FSP"			
<a href="#">5050154002</a>	NO			"1193815-7", "RNF-100-NO.302-BK-SP"			
<a href="#">5050964002</a>	NO			"9-1193817-4", "RNF-100-NO.301-BK-SP"			
<a href="#">5051514001</a>	NO			"3-1193819-9", "RNF-100-NO.300-BK-SP"			
<a href="#">5052934106</a>	NO			"2-1193826-7", "RNF-100-1/16-WH-SP"			
<a href="#">5052984151</a>	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
<a href="#">5053034137</a>	NO			"5-1193837-2", "RNF-100-1/8-WH-SP"			
<a href="#">5053054039</a>	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
<a href="#">5053064084</a>	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
<a href="#">5053074047</a>	NO			"2-1193843-9", "RNF-100-3/16-BU-SP"			
<a href="#">5053084107</a>	NO			"9-1193843-5", "RNF-100-3/16-WH-SP"			



Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5053104060</a>	NO			"4-1193848-9", "RNF-100-1/4-RD-SP", "RNF-100-1/4-2"			
<a href="#">5053134121</a>	NO			"7-1193851-1", "RNF-100-1/4-WH-SP"			
<a href="#">5053394065</a>	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
<a href="#">5053444034</a>	NO			"6-1193887-4", "RNF-100-3-BK-SP"			
<a href="#">5053494030</a>	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
<a href="#">5070024041</a>	NO			"3-1193959-4", "RNF-100-1/16-CL-SP"			
<a href="#">5070044083</a>	NO			"1193961-7", "RNF-100-1/8-CL-SP"			
<a href="#">5070054057</a>	NO			"RNF-100-3/16-CL-SP", "1832014-1"			
<a href="#">5070064069</a>	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
<a href="#">540963-000</a>	NO			"7-1194242-7", "RNF-100-3/8-BK-FSP"			
<a href="#">769283-000</a>	NO			"4-1195994-9", "RNF-100-3/8-WH-FSP"			
<a href="#">9053854002</a>	NO			"2-1197035-2", "RNF-100-NO.301-CL-SP"			
<a href="#">911779-000</a>	NO			"2-1197081-1", "RNF-100-3/8-CL-FSP"			
<a href="#">969515-000</a>	NO			"4-1197495-3", "RNF-100-1-WH-FSP"			