

# BOURNS®

## Product Update Memo


### RESISTOR NETWORKS

May, 2012


## Pin One Marking Change

Effective with manufacturing date code 1219, the mark designating pin one on components for Bourns® [Model 41xx, 43xx, 44xx, and 48xx resistor networks](#) will change from a laser marked square to a laser marked round dot.

This is a running change and there may be packaging with either of the two marks in the same shipment. There is no change to form, fit or function.



*Before*



*After*

Please contact your local [Bourns Representative](#) or [Bourns Customer Service](#) for further information.