

**1 Products affected**

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	005	116	0000001135	See list below	Connectors	GSF1 POWER ENTRY MODUL 10A	n/a

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)


List of part numbers affected

GSF1.0021.31	GSF1.0022.31	GSF1.0023.01	GSF1.0123.01	GSF1.0211.31
GSF1.0221.01	GSF1.0221.31	GSF1.0222.31		

**2 Type of change**

Change marking.

**3 Detailed description of change**



**4 Reason of change**

Rear cover version suitable without fuse. Therefore the inscription "FUSE" removed.

**5 Release date**

The change will be rolled-out starting ww 40/2020 (Date code 2040 or higher on label) and lasts approx. 6 months depending on the variant.

**6 Impact of change and recommended action**

Form	Yes	Change of marking.
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

Product Change Notification						GSF1 with cover text "Fuse" removed	
owner	creation date	release date	released by	change order no	rev	page	D10-047-541
sariogar	06.08.2020	11.12.2020	muehlema	2018470	A	1 of 2	

**7 Reference Documents / Attachments**

Kind of document	Remarks
<a href="#">GSF1 Data sheet</a>	

<b>Product Change Notification</b>					<b>GSF1 with cover text "Fuse" removed</b>		
owner	creation date	release date	released by	change order no	rev	page	D10-047-541
sariogar	06.08.2020	11.12.2020	muehlema	2018470	A	2 of 2	