



Product Discontinuation Notification

PDN#21-14- Discontinuation of selected PTS Tactile Products

C&K

Office 1007-8, 10/F, Harcourt House, 39 Gloucester Road, Wanchai, Hong Kong
Tel: +852 3713 5288 ckswitches.com

Document subject to change without prior notice



Document revision

| Revision | Date | Description | Author |
|----------|-----------|--|-----------|
| A | 2021/4/27 | Discontinuation of selected PTS Tactile Products | Daisy Liu |



Summary

| | |
|--------------------------------------|---|
| 1. Purpose | 4 |
| 2. Discontinuation details..... | 4 |
| 2.1 Part References affected..... | 4 |
| 2.2 Possible replacement | 5 |
| 2.3 Reason for discontinuation | 5 |
| 3. Date of application | 5 |
| 4. Acknowledgement | 5 |
| 5. Support | 5 |

1. Purpose

This notification is to announce the discontinuation of the below listed P/Ns in PTS series.

2. Discontinuation details

2.1 Part References affected

| P/N | Description |
|-----------------|-----------------------|
| Y96A112M0FP | PTS125SM85 |
| Y96J13KK0FP LFS | PTS125VJK73 LFS |
| Y96A114F0FP | PTS125SK85 |
| Y96M462C1FP LFS | PTS641TM31SMTR2 LFS |
| Y96M262C1FP LFS | PTS641TM31SMTR LFS |
| Y96A262C1FP | PTS641TM31 |
| Y96M464C1FP LFS | PTS641TK31SMTR2 LFS |
| Y96M252C1FP LFS | PTS641SM31SMTR LFS |
| Y96M254C1FP LFS | PTS641SK31SMTR LFS |
| Y96F284B1FP | PTS640XK25SS-FORM |
| Y96F284B1FP LFS | PTS640XK25SS-FORM LFS |
| Y96E254B1FP | PTS638SK25SMTR |
| Y96E254B1FP LFS | PTS638SK25SMTR LFS |
| Y96D131E0FP LFS | PTS635VL39 LFS |
| Y96D131C0FP LFS | PTS635VL31 LFS |
| Y96D133E0FP LFS | PTS635VH39 LFS |
| Y96D133C0FP LFS | PTS635VH31 LFS |
| Y96D111G0FP | PTS635SL50 |
| Y96D111G0FP LFS | PTS635SL50 LFS |
| Y96L251F1FP | PTS635SL43SMTR |
| Y96L251F1FP LFS | PTS635SL43SMTR LFS |
| Y96D111F0FP | PTS635SL43 |
| Y96D111F0FP LFS | PTS635SL43 LFS |
| Y96L251B0FP | PTS635SL25SM |
| Y96L251B0FP LFS | PTS635SL25SM LFS |
| Y96L254F1FP | PTS635SK43SMTR |
| Y96L254B1FP LFS | PTS635SK25SMTR LFS |
| Y96L254B0FP LFS | PTS635SK25SM LFS |
| Y96D113G0FP | PTS635SH50 |
| Y96D113G0FP LFS | PTS635SH50 LFS |
| Y96L253F1FP | PTS635SH43SMTR |
| Y96L253F1FP LFS | PTS635SH43SMTR LFS |
| Y96D113F0FP | PTS635SH43 |
| Y96D113F0FP LFS | PTS635SH43 LFS |

| | |
|-----------------|--------------------|
| Y96C252Q1FP | PTS525SM10SMTR |
| Y96C252Q1FP LFS | PTS525SM10SMTR LFS |
| Y96C252Q0FP | PTS525SM10SM |
| Y96C252P1FP | PTS525SM08SMTR |
| Y96C252P1FP LFS | PTS525SM08SMTR LFS |
| Y96C254Q1FP | PTS525SK10SMTR |
| Y96C254Q1FP LFS | PTS525SK10SMTR LFS |
| Y96C254Q0FP | PTS525SK10SM |
| Y96C254P1FP | PTS525SK08SMTR |
| Y96C254P1FP LFS | PTS525SK08SMTR LFS |
| Y96B111D0FP | PTS453SL38 |
| GSPTS0035 | PTS846GKSMTR2 LFS |

2.2 Possible replacement

Please contact your local Sales Representative or C&K Technical Solutions Manager

2.3 Reason for discontinuation

With the world's widest selection of switch products it is critical that we keep our Portfolio current and relevant to our customers. Many of the parts above have very similar capabilities and specifications to other parts within the PTS family of products, but are not as popular. As such they are no longer commercially viable to produce.

3. Date of application

- Last Time Buy: 30th Nov, 2021
- Last Delivery: 30th May, 2022
- Date of Discontinuation: 30th May, 2022

4. Acknowledgement

We kindly ask you to acknowledge this information to your Sales Representative.

5. Support

For any question, please contact your C&K regional sales representative.