



KYOCERA International, Inc.
46723 Five Mile Rd.
Plymouth, MI 48170
Tel: 248-921-0410
<http://americas.kyocera.com>

Notice of End of Life #10152019

KYOCERA Connector Product

Dear Customer,

October 15th 2019 - Kyocera International Inc. would like to inform you about end of life for the below connector part numbers located in Table 1. This EOL takes effect immediately.

Table 1, located at the bottom of this document includes a list of known part numbers sold within the North American market along with a suggested replacement if available.

We apologize for the inconvenience and thank you for your understanding and cooperation.

Sincerely,

Bill Adam

Distribution Account Manger

KYOCERA International Inc.

Bill.Adam@kyocera.com

Table 1:

Series	Kyocera Part Number	Description	Replacement
8283	008283027000808L	Wire to Board	None
8283	008283037000808L	Wire to Board	None
8283	008283047000808L	Wire to Board	None
8283	008283057000808L	Wire to Board	None
8283	008283067000808L	Wire to Board	None
8283	008283077000808L	Wire to Board	None
8283	008283087000808L	Wire to Board	None
8283	008283097000808L	Wire to Board	None
8283	008283107000808L	Wire to Board	None
8283	008283117000808L	Wire to Board	None
8283	008283127000808L	Wire to Board	None
8283	008283137000808L	Wire to Board	None