

PRODUCT CHANGE NOTIFICATION

Product Category XMR TIES & TOOLS 20221122-1

Product Group PLASTIC CABLE TIES

ISSUE DATE: 22-Nov-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Effective immediately, Panduit will be discontinuing production of PAT2S and PAT3S systems. The following part numbers will no longer be manufactured:

- PAT2S tool head
 - PAT3S tool head
 - PDS, PDS-EI, PDS-DI, PDS-EI-DI dispensers
 - ~~PD3S PD3S EI PD3S DI PD3S EI DI dispensers~~
- Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2022	12	16

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Replacement Part 1	Discontinuation Date
PAT2S	NO-REPLACEMENT	16-Dec-22
PAT3S	NO-REPLACEMENT	16-Dec-22
PDS	NO-REPLACEMENT	16-Dec-22
PDS-EI	NO-REPLACEMENT	16-Dec-22
PDS-DI	NO-REPLACEMENT	16-Dec-22
PDS-EI-DI	NO-REPLACEMENT	16-Dec-22
PD3S	NO-REPLACEMENT	16-Dec-22
PD3S-EI	NO-REPLACEMENT	16-Dec-22
PD3S-DI	NO-REPLACEMENT	16-Dec-22
PD3S-EI-DI	NO-REPLACEMENT	16-Dec-22
PDSF	NO-REPLACEMENT	16-Dec-22
PD3SF	NO-REPLACEMENT	16-Dec-22
PATSBM	NO-REPLACEMENT	16-Dec-22
PD-RC	NO-REPLACEMENT	16-Dec-22