PRODUCT NEWS

Product Discontinuation Notices

Basic Switches, Detection Switches, Door Switches / Power Switches

OMRON

Issue Date March 1, 2021

No. 2021022CE(ON)

Discontinuation Notice of Part of Common Accessories Model VAL, Model VAM, Model VAV, Low-torque Basic Switch Model D2MC, Miniature Basic Switch Model D2RV, Model VN, VX, Subminiature Basic Switch Model SSG, SSN, Ultra Subminiature Basic Switch Model D2MQ, Model J, Detection Switch Model D2X.

Product Discontinuation

Common Accessories
Model VAL

Model VAM Model VAV

Low-torque Basic Switch

Model D2MC-5E1

Miniature Basic Switch

Model D2RV-LEB Model VN

Model VX

Subminiature Basic Switch

Model SSG

Model SSN

Ultra Subminiature Basic Switch

Model D2MQ Model J-7Y-V

Detection Switch

Model D2X

No recommended replacement Model VAM Model VAV

Model VAL or

Low-torque Basic Switch

Recommended Replacement

Common Accessories

Model D2MC-5E

Miniature Basic Switch

No recommended replacement No recommended replacement No recommended replacement

Subminiature Basic Switch

Model SSG or No recommended replacement Model SSN

Ultra Subminiature Basic Switch

No recommended replacement Model J-7-V

Detection Switch No recommended replacement

[Final order entry date]

The end of March, 2022

[Date of The Last Shipping]

The end of June, 2022

[Caution on recommended replacement]

Not specifically.





[Difference from discontinued product]

Recommended replacement Model	Body Color	Dimen- sions	Wire connection	•		Operation ratings	Operation methods
Please refer to the list	**	*	*	*	*	*	**

** : Compatible* : The change is a little/Almost compatible

-- : Not compatible- : No corresponding specification

[Product Discontinuation and recommended replacement]

Product discontinuation	Recommended replacement
VAL(-)	VAL
VAL2(-)	VAL2
2VAL2	No recommended replacement
2VAL02	No recommended replacement
VAM21(-)	VAM21
VAV(-)	VAV
VAV2(-)	VAV2
VAV-5(-)	VAV-5
D2MC-5E1	D2MC-5E
D2RV-LEB	No recommended replacement
V-152-6A5-T	No recommended replacement
V-16G-2C25-L(R) FOR SHARP MWO2	No recommended replacement
V-16G-3C25-L(R) FOR SHARP MWO2	No recommended replacement
V-16G-2C25-L(R) NISSHIN	No recommended replacement
V-16G-3C25-L(R) NISSHIN	No recommended replacement
V-16G-3C25-L(R) ACME	No recommended replacement
V-16G-2C25-L(R) ACME	No recommended replacement
V-16G-1C25-L(R) FOR SHARP MWO	No recommended replacement
V-16G-3C25-L(R) 2 OEP	No recommended replacement
V-16G-2C25-L(R) 2 OEP	No recommended replacement
V-165-1D55-L	No recommended replacement
V-165-1D65-L	No recommended replacement
V-16G-2C5-L	No recommended replacement
V-16G-3C5-L	No recommended replacement
V-16G1-3C25-L	No recommended replacement
V-166-1D55-L	No recommended replacement
V-166-1D65-L	No recommended replacement
V-163-3C5-L	No recommended replacement
V-163-3C25-L	No recommended replacement
V-16G-3C25-L(R) 2	No recommended replacement
V-16G-2C25-L(R) 2	No recommended replacement
V-16G1-1C25-L	No recommended replacement
V-161-1C5-L	No recommended replacement
V-161-3C5-L	No recommended replacement
V-16-1D55-L	No recommended replacement
V-16-1D65-L	No recommended replacement
V-16-2D55-L	No recommended replacement
V-16-2D65-L	No recommended replacement
V-16-3D55-L	No recommended replacement
V-16-3D65-L	No recommended replacement

OMRON

Product discontinuation	Recommended replacement
V-162-3C5-L	No recommended replacement
V-16-3C25-L	No recommended replacement
V-16-1C5-L	No recommended replacement
V-16-2C5-L	No recommended replacement
V-16-3C5-L	No recommended replacement
V-16-1C5-L(R01)	No recommended replacement
V-16-2C5-L(R01)	No recommended replacement
V-16-3C5-L(R01)	No recommended replacement
V-16G-2C25-L(R)	No recommended replacement
VX-51K-1C22	No recommended replacement
VX-53-1C22	No recommended replacement
SSG-01L12H	SSG-01L1H
SSG-01L37P	No recommended replacement
SS-5GL13-L コイルバネ	SS-5GL13
SS-01GL1131	SS-01GL
D2MQ-4R-R	No recommended replacement
D2MQ-4L-L	No recommended replacement
J-7Y-V	J-7-V
D2X-U1112499EI BY OMI	No recommended replacement
D2X-U1245271EI BY OMI	No recommended replacement
D2X-U1245270EI BY OMI	No recommended replacement
D2X-U1245514EI BY OMI	No recommended replacement
D2X-U1245532KD BY OMI	No recommended replacement
D2X-U1245281EI BY OMI	No recommended replacement
D2X-U1245235EI BY OMI	No recommended replacement
D2X-U1245306EI BY OMI	No recommended replacement
D2X-U1112498EI BY OMI	No recommended replacement
D2X-U1245201EI BY OMI	No recommended replacement
D2X-U1112498KD BY OMI	No recommended replacement
D2X-U1112499KD BY OMI	No recommended replacement
D2X-U1245531KD BY OMI	No recommended replacement

Specifications and prices in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.