

PRODUCT DISCONTINUATION

#PD-IF-PIRZ-13

Business Unit	Product Line Code	Type of Change	Action	Date of issue
IF	CK6	Discontinuation	Notify Distributors and Field	5/24/2013

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

The following part numbers are being discontinued by Phoenix Contact.
 Please note: replacement parts have been identified where available.

Warranty Information:

N/A

Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? N/A

Transaction Dates:

Last Buy from Phoenix Contact: 10/31/2013

Last Scheduled Ship from Phoenix Contact: 4/30/2014

PRODUCT DISCONTINUATION

Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

MARK BUCKLEY
 Product Specialist - Interface
 (717)944-1300 x3251
 mbuckley@phoenixcon.com

Thank you,



Jeremy Valentine,
 Product Marketing Manager

Discontinued Part#	Type Description	Replacement Part#
2963530	ELR-PB-GATEWAY	---
2900553	ELR H3-ES-SC-230AC/500AC-2	2900568
2900555	ELR H3-ES-SC-230AC/500AC-9	2900570
2900688	ELR H5-ES-SC-230AC/500AC-0,6	2900420
2900562	ELR H5-ES-SC-230AC/500AC-9	2900422
2900686	ELR H3-ES-SC-230AC/500AC-0,6	2900689
2900560	ELR H5-ES-SC-230AC/500AC-2	2900689
2970549	UMK- E48F-VS/TP(1,6X0,8)L	---
2288477	FLKM 50-W80/ 80/PLC	---