

PRODUCT DISCONTINUATION

#PD-IFC-9M7B-16

Business Unit	Product Line Code	Type of Change	Action	Date of issue
IFC	BF7	Electrical	Notify Distributors and Field	2/15/2016

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

HEAVYCON's original B-Series screw termination contact inserts will be discontinued and replaced with a significantly improved version. Benefits of the new design include:

- Improved test points up to a 2 mm test pin.
- Improved UL current values. Old UL(USR) / CUL(CNR) : 13 / 13 Amps.
New UL(USR) / CUL(CNR) : 16 / 14 Amps.
- Improved IEC current values. B6 and B10 inserts up to 24 Amps.
B16 and B24 inserts up to 20 Amps.
- Approved for railway vehicles. Now comply with DIN EN 45545-2 with the R22, R23 and R24 requirements set in the hazard level HL1, HL2 and HL3.
- Plastic material changed from glass fiber reinforced PA to industry standard glass fiber reinforced PC.
- New quick-connect coding pins (red tabs) provide fast mechanical keying to prevent identical hood and base connectors from being mis-mated.

All new contact inserts will be fully compatible with existing B-series inserts, both from Phoenix Contact as well as other suppliers.

Warranty Information:

N/A

Stock Status

Can existing stock still be used? Y








Is mixture of stock acceptable? N

Transaction Dates:

Last Buy from Phoenix Contact: 4/1/2016

Last Scheduled Ship from Phoenix Contact: 9/30/2016

PRODUCT DISCONTINUATION

Previous Product	(if applicable)	New Product
		
		
		
		


PRODUCT DISCONTINUATION

Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

STEVEN OBERT
 IFC Marketing Lead Specialist
 (717)944-1300x3250
 sobert@phoenixcon.com

Thank you,



Loreen E. Katz, Product Marketing Manager

Discontinued Part#	Type Description	Replacement Part#	Type Description
1771037	HC-B 6-ESTS	1648115	HC-B 6-I-UT-M
1771011	HC-B 6-EBUS	1648128	HC-B 6-I-UT-F
1771228	HC-B 10-ESTS	1648173	HC-B 10-I-UT-M
1771202	HC-B 10-EBUS	1648186	HC-B 10-I-UT-F
1771480	HC-B 16-ESTS	1648238	HC-B 16-I-UT-M
1771464	HC-B 16-EBUS	1648241	HC-B 16-I-UT-F
1775622	HC-B 16-ESTS 32	1584871	HC-B 16-I-UT-M-32
1775619	HC-B 16-EBUS 32	1584884	HC-B 16-I-UT-F-32
1771749	HC-B 24-ESTS	1648296	HC-B 24-I-UT-M
1771723	HC-B 24-EBUS	1648306	HC-B 24-I-UT-F
1772104	HC-B 24-ESTS 48	1584936	HC-B 24-I-UT-M-48
1772094	HC-B 24-EBUS 48	1584949	HC-B 24-I-UT-F-48