



Product Discontinuance Notice - PDN 18_0049 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinuation of HMC875

Publication Date: 25-Jun-2018

Last Time Buy Date: 25-Jun-2019

Last Time Ship Date: 25-Jun-2020

Revision Description:

Initial Release

Reason For Discontinuance

Product is tested in Colorado and due to lack of sales we will not spend resources on transferring the test to ADGT, therefore the product will be discontinued.

Comments

The ADCMP580 should be considered for replacement of HMC875.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas:	PDN_Americas@analog.com	Europe:	PDN_Europe@analog.com	Japan:	PDN_Japan@analog.com
		Rest of Asia:			PDN_ROA@analog.com

PDN 18_0049 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
125932-HMC875LC3C	HMC875	EVAL-ADCMP580BCPZ	No	Similar but not exact same data sheet specifications
HMC875LC3C	HMC875	ADCMP580BCPZ-WP	No	Similar but not exact same data sheet specifications
HMC875LC3CTR	HMC875	ADCMP580BCPZ-RL7	No	Similar but not exact same data sheet specifications
HMC875LC3CTR-R5	HMC875	ADCMP580BCPZ-RL7	No	Similar but not exact same data sheet specifications

Appendix A - PDN 18_0049 Revision History

Rev	Publish Date	Rev Description
Rev. -	25-Jun-2018	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:1280 Layout Rev:2 Parent DocId:None