



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000832I

DATE: 20-Jan-2015

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	MAX268ACWG	MAX268ACWG+	20-Jan-2015	19-Jan-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX4199ESA	MAX4199ESA+	20-Jan-2015	19-Jan-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX4131EPA	N/A	20-Jan-2015	19-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4199ESA+W	N/A	20-Jan-2015	19-Jan-2017	The part was not released
Discontinuance	MAX4269EEE	N/A	20-Jan-2015	19-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4269ESD	N/A	20-Jan-2015	19-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4288ESD-T	N/A	20-Jan-2015	19-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4288EUB	N/A	20-Jan-2015	19-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4288EUB-T	N/A	20-Jan-2015	19-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX44282AKA+	N/A	20-Jan-2015	19-Jan-2017	The part was not released
Discontinuance	MAX44282AKA+T	N/A	20-Jan-2015	19-Jan-2017	The part was not released
Discontinuance	MAX44283AKA+	N/A	20-Jan-2015	19-Jan-2017	The part was not released
Discontinuance	MAX44283AKA+T	N/A	20-Jan-2015	19-Jan-2017	The part was not released
Discontinuance	MAX987EUK-G05	N/A	20-Jan-2015	19-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX987EUK-TG05	N/A	20-Jan-2015	19-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX987EUK.C60328	MAX987EUK+T	20-Jan-2015	19-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Feb-2015