



M5STACK

Product Change Notification

| | | | |
|--|----------------|---|-------------|
| PCN# | PCN20201228-01 | PCN ISSUE DATE | Dec 28 2020 |
| PCN TITLE: | | | |
| RoverC PCN | | | |
| TYPE OF CHANGE | | | |
| <input type="checkbox"/> Electrical Specification | | <input checked="" type="checkbox"/> Part Number | |
| <input checked="" type="checkbox"/> Mechanical Specification | | <input type="checkbox"/> End of Life | |
| <input type="checkbox"/> Firmware Specification | | <input type="checkbox"/> Other | |
| <input type="checkbox"/> Regulatory of Compliance | | | |
| AFFECTED PART NUMBER(S) | | | |
| Part Number | | Name | |
| K036 | | RoverC | |
| CHANGE DESCRIPTION | | | |
| Change From: | | | |
| Part Number | Name | Image | |
| K036 | RoverC | | |
| Change To: | | | |
| Part Number | Name | Image | |
| K036-B | RoverC Pro | | |
| DESCRIPTION OF CHANGE | | | |
| <ol style="list-style-type: none"> 1. Add one Servo Gripper 2. Add two Servo Ext Port 3. Battery removable | | | |
| SUPPLYING SCHEDULE | | | |
| Dec 28 th , 2020 | | | |
| REASONS FOR CHANGE | | | |
| Due to switch button are easy to fall off during transportation, this product needs to be removed from the shelf for updating. The new version is expected to be completed in Q1 2021. | | | |
| CUSTOMER ACTION REQUIRED | | | |
| Product sold on customer website needs to be updated after stock consumed. | | | |