



Not Recommended for New Design: NN31xxx Series

NRFND.PG33.05.31.2018

05.31.2018

About This Notice:	Effective immediately, the below Panasonic parts are Not Recommended For New Design due to a high possibility of built-in components discontinuation.
Features:	
Effective Date:	May 31, 2018
Affected Parts and/or Replacements:	NN31000A-BB NN31001A-BB NN31002A-BB
Datasheet(s):	https://industrial.panasonic.com/content/data/SC/ds/ds4/NN31000A_E.pdf https://industrial.panasonic.com/content/data/SC/ds/ds4/NN31001A_E.pdf https://industrial.panasonic.com/content/data/SC/ds/ds4/NN31002A_E.pdf
Notes:	