

## Product Change Notification (PCN)

PCN Number	501519	Date Issued	March 06, 2017
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change will affect the fit, form, function or appearance of the parts. Or, it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	No change to parts/components FFF		
Internal Molex Qualification Date	November 30, 2016		
Sample Availability Date (Changed Part)	November 30, 2016		
Planned Implementation Date	December 01, 2016		
Method of Identifying Change	Date code		

RELEASED



## Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:501519**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

The change subject is remove UL label paste on reel of Ribbon wire, No impact to product form fit or function.

Please be inform production will create another PCN to replace this one with before and after information in customer letter as below:

### Before Change

- Reel of Ribbon wire with UL processed wire respooled label



### After Change

#### Overview

- This PCN is to replace PCN 501519 detail of before and after
- REMOVE, UL PROCESSED WIRE RE ribbon cable is not in UL PROCESS
- Product Impact
  - no impact to any fit, form or f
- Part Number Impact
  - see attached impacted parts l

Molex Part #

82226102

82226104

82283020

82283040

82286161