

## Global Change Notification (GCN)

Product Family	MX150	10688392
		GCN Number
Series	34062	June 01, 2015
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	This letter is to inform you that, due to increasing volumes of the GFI Receptacle Connector, an additional Ring Seal mold is being fabricated for capacity. This is strictly capacity tooling with no design or material changes.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	New Capacity	
Assessment Of Change (How Product Will Be Qualified & Validated)	validation testing	
Internal Molex Qualification Date (Planned Date Information Available)	June 01, 2015	
Sample Availability Date (Changed Part)	June 01, 2015	
Date of Implementation	July 02, 2015	
Method of Identifying Change	unique cavity ID numbers	
Recommended Replacement Parts	NA	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)