



## MICRON\_Module Assembly Site Addition of TSMT (Taiwan)

PCN: 34197

Published: 2021-06-18

**Type:** Additional Source/Supplier, Manufacturing Site - Change or Addition

**Description:** Micron is adding Module assembly site as indicated below:

**Current Module Assembly:**

MXA: Micron Semiconductor Xi'an Co., Ltd., Zone B of Shaanxi Xi'an Export Processing Zone, Xin Xi Avenue, Xi'an, 710119 China (PRC)

**Future Module Assembly (can be either of the below locations):**

MXA: Micron Semiconductor Xi'an Co., Ltd., Zone B of Shaanxi Xi'an Export Processing Zone, Xin Xi Avenue, Xi'an, 710119 China (PRC)

**TSMT:** Taiwan Surface Mounting Technology Corp, No. 437, Taoying Rd., Taoyuan City, Taoyuan County 330, Taiwan (R.O.C.)

**Reason:** Additional Source/Supplier, Supply Flexibility/Security

**Product Affected:** Z22A and Z11B module part numbers listed below

Affected Micron Part Number	Recommended Replacement	Customer Part Number
<u>MODULE</u>		
MTA16ATF4G64AZ-3G2B1		
MTA16ATF4G64HZ-2G6B4		
MTA18ADF4G72AZ-3G2B3		
MTA18ASF2G72HZ-2G6E4		
<b>MTA18ASF4G72AZ-2G6B1</b>		<b>557-MTA18ASF4G72AZ-2G6B1-ND</b>
MTA36ASF8G72LZ-3G2B1		
MTA4ATF1G64HZ-3G2B2		
MTA8ATF2G64AZ-3G2B1		
MTA8ATF2G64HZ-3G2B2		
MTA9ASF1G72HZ-2G6E5		

\*Materials that have been ordered are in **bold**.

**Method of Identification:** Manufacturing location indicated on the module label. Please refer to CSN-11 for details.

**Micron Sites Affected:** Subcontractor

**Sample Available:** 2021-07-27

**Qual Data Available:** 2021-07-27

**Product Ship Date:** 2021-10-25

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

**Micron Confidential and Proprietary Information**

## Attachments

---

There are no attachments on this PCN