

Light is OSRAM


Not For New Design OS-NFND-2021-030

15 November 2021

Expected discontinuation date: 1-5 Years

Reason: The following products have reached their end of life.

OSRAM OS Expectations: Please use our recommended replacement for new designs. If they may not fit, please contact your local sales office for other solutions. Additionally we ask you to switch for running project as soon as possible to the proposed replacement. Anyway please check your demand and feedback your requested lifetime of these products.
Attention: Q# already announced to be in phase-out process will not be impacted. Dates published in corresponding PDN will be kept.



Please direct your feedback to your local Sales office.

Not for new design products			Recommended Replacement		
Device	Brand	Expected PDN start	Device	Brand	Datasheet Ordering Code
SFH 3201-Z	Reflective Interrupter	November 2022	none		
SFH 3201-2-Z	Reflective Interrupter	November 2022	none		
SFH 3201-3-Z	Reflective Interrupter	November 2022	none		
SFH 3201-2/3-Z	Reflective Interrupter	November 2022	none		

Ordering Code Notification	Device	Product Descr.	Exp. PDN Date	Repl. Ordering Code
Q65110A1207	OS-NFND-2021-030 SFH 3201	SFH 3201-Z	11/1/2022	NO REPLACEMENT
Q65110A2476	OS-NFND-2021-030 SFH 3201	SFH 3201-2-Z	11/1/2022	NO REPLACEMENT
Q65110A2477	OS-NFND-2021-030 SFH 3201	SFH 3201-3-Z	11/1/2022	NO REPLACEMENT
Q65110A2479	OS-NFND-2021-030 SFH 3201	SFH 3201-2/3-Z	11/1/2022	NO REPLACEMENT