



Product Change Notification

TE Connectivity

Product Change Notification: P-19-017493

PCN Date: 12-JUN-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing Location Change Appliances Tubing HRHF Products

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from Menlo Park, USA to Trutnov, CZ. Different parts will move in different phases, consequently not all new part numbers will be immediately available at the end of the notification period.

Other attachments:

[PCN HRHF additional information.](#)

[PCN HRHF Packaging information.](#)

Reason for Changes:

Dear Customer, we hereby inform you about a transfer of processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. Upon request, a PPAP Level 2 will be available if it concerns a transfer of a process which produces a finished TE-product. If you require such a PPAP, please notify the responsible TE Sales Contact within 14 calendar days after receipt of this PCN.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	02-SEP-2019
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2019

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5099-000	NO						
CB5101-000	NO			"HRHF-125CL-10", "1-1899833-8"			
CB5105-000	NO						
CB5106-000	NO						
CB5107-000	NO			"HRHF-125FR-10/97", "3-1899833-5"			
CB5122-000	NO			"HRHF-200FR-10/97", "5-1192468-6"			
CB5128-000	NO						
CB5129-000	NO			"HRHF-250FR-10/97"			
CF6155-000	NO						
CF6163-000	NO						
CF6166-000	NO			"9-1191306-3"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5122-000	NO			"HRHF-200FR-10/97", "5-1192468-6"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5099-000	NO						
CB5101-000	NO			"HRHF-125CL-10", "1-1899833-8"			
CB5105-000	NO						
CB5106-000	NO						
CB5107-000	NO			"HRHF-125FR-10/97", "3-1899833-5"			
CB5122-000	NO			"HRHF-200FR-10/97", "5-1192468-6"			
CB5128-000	NO						
CB5129-000	NO			"HRHF-250FR-10/97"			
CF6163-000	NO						
CF6166-000	NO			"9-1191306-3"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5099-000	NO						
CB5101-000	NO			"HRHF-125CL-10", "1-1899833-8"			
CB5105-000	NO						
CB5106-000	NO						
CB5107-000	NO			"HRHF-125FR-10/97", "3-1899833-5"			
CB5122-000	NO			"HRHF-200FR-10/97", "5-1192468-6"			
CB5128-000	NO						
CB5129-000	NO			"HRHF-250FR-10/97"			
CF6163-000	NO						
CF6166-000	NO			"9-1191306-3"			