



520 Park East Blvd., New Albany, IN 47150 U.S.A
(812)-944-6733 / 1-800-SAMTEC9

Product Change Notification

1. ECR #: 159202
Notification #: 315


2. Date of Announcement: November 14, 2017

3. Series:
• MODP - MODP

4. Part #'s Affected
• MODP-01-8P8C-S-01

5. Description of Change:
Modifying the tail end of the shielding and fixing the problem of uneven length in its tail. The specification, the measurement and the functionality of the product remain the same. Only the appearance of the shielding has been slightly changed.

6. Method of Identifying Change
Visual inspection.



7. Reason for Change:
The existing design has the tail end of the shielding uneven in its length. This change is to improve the manufacturability (DFM).

8. Impact of Change on Form, Fit, or Function:
• Form - shielding changed.

9. Projected Implementation Date: January 08, 2018

Disclaimer

Please review the change notification details listed above for specific information regarding the nature and timing of the change. While Samtec has taken precautions to ensure this change is not detrimental to your application, each application can be unique and therefore customers should consider the effect of the change on their specific application.

Samtec has taken efforts to ensure that all users of this product who have requested change notifications have been informed. However, you should assume that this is the only notification that will be sent and you, as the recipient, must determine how to communicate this information to your organization(s) and customer(s) as appropriate. If you wish to opt out of receiving Samtec Engineering Change Notification emails, please contact CustomerECN@samtec.com. Due to technical progress, specifications are subject to change without notification and it is recommended to provide an alternative contact when opting out.

Please contact Samtec at CustomerECN@samtec.com for any questions related to this change.