

Sensing and Control
1985 Douglas Drive North
Golden Valley, MN 55422
1-815-235-5500

March 3, 2014

Subject: Announcing Relialign™ RDI2 Series Residential Door Interlock Obsolescence

Honeywell Sensing and Control (S&C) has made obsolete the Relialign™ RDI2 Series Residential Door Interlock, and is no longer accepting orders for this product. Honeywell offers the alternate Relialign™ RDI Series Residential Door Interlock as a replacement to the RDI2 Series product.

Affected Listings and Applicable Replacements

Current Part Numbers	Proposed Replacement Part Numbers
RDI2LBP1	RDI-H-LP
RDI2LBP1-TK	RDI-H-LP
RDI2LBP2	RDI-H-L5P
RDI2LBP2-1	RDI-H-L5P1
RDI2LBP2-TK	RDI-H-L5P
RDI2LBS1	RDI-H-L
RDI2LBS2	RDI-H-L5
RDI2RBP1	RDI-H-RP
RDI2RBP1-TK	RDI-H-RP
RDI2RBP2	RDI-H-R5P
RDI2RBP2-1	RDI-H-R5P1
RDI2RBP2-TK	RDI-H-R5P
RDI2RBS1	RDI-H-R
RDI2RBS2	RDI-H-R5

Important Dates

February 20, 2014: Effective this date, Honeywell is no longer taking orders for these RDI2 products. All open orders will be cancelled

Contact Information

Contact information for Honeywell Customer Service Representatives

North America:	+1 (800) 537 6945	Taiwan:	+886 (2) 2245 1000
Europe:	+44 (0) 1698 481481	Singapore:	+65 (6) 255 2828
Shanghai:	+86 (21) 2219 6888	Australia:	+61 (2) 9353 7810
Seoul:	+82 (2) 799 6159	India:	+91 (20) 6603 9400

Tokyo: +81 (3) 6730 7208

Best regards,

Tom Werner

Tom Werner
Senior Product Marketing Manager