


Product Change Notification (PCN)

PCN Number	502553	Date Issued	March 10, 2017
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change will affect the fit, form, function or appearance of the parts. Or, it may result in a change to the specification. The pictures below show an example of the possible differences.		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports are available upon request.		
Internal Molex Qualification Date	March 10, 2017		
Sample Availability Date (Changed Part)	March 10, 2017		
Planned Implementation Date	October 02, 2017		
Method of Identifying Change	New part number		

RELEASED

Before Change

After Change



Overview

- For continuous improvement, Molex will be upgrading the Mat Seal within the MX150 2x8 Blade for seal tear reduction
- Product Impact
 - Mat seal hole geometry and hole location optimization
 - Seal color change from rust red to royal blue
 - No change to hole diameter
 - Material will remain the same inherently lubricated silicone
- Part Number Impact
 - 33482-16xx, 33482-17xx & 33482-18xx will become obsolete, replaced by 33482-86xx, 33482-87xx & 33482-88xx respectively
- PPAP and samples available upon request



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:502553**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Part Number Affected:
33482-1601