

Product Change Notice

Issue Date: 01-April-2021

Change Description:

Introduction of new dice sources

Parts Affected:

Group 1

ASMT-UAB4-YU7C2	ASMT-UAB4-ZU8J2	QSMT-URSD-YVB02	QSMT-JAAZ-ZV2C2
ASMT-UAB4-YU802	ASMT-UAB4-ZV3H2	QSMT-UAA4-PUCJ2	QSMT-JALM-ZV2C2
ASMT-UAB4-YU8E2	ASMT-UAB4-ZV3C2	ASMT-UAA4-YV3C2	QSMT-JAAE-ZV3C2
ASMT-UAB4-YV3C2	ASMT-UHB4-ZU802	QZMT-UAA4-PUCJ2	QSMT-JAAT-ZV3C2
ASMT-UHB4-YU8A2	ASMT-UHB4-ZV302	QSMT-UAAZ-ZU7C2	QSMT-JAAZ-ZV3C2
ASMT-URB4-YU802	ASMT-URB4-ZU802	ASMT-JAB4-ZU7H2	ASMT-JHB4-ZU802
ASMT-URB4-YV302	ASMT-URB4-ZV302	ASMT-JAB4-ZU7C2	ASMT-JHB4-ZV302
ASMT-UAB4-ZU4H2	QSMT-UAJ1-ZU4H2	ASMT-JAB4-ZV3C2	ADMT-URA4-ZV302
ASMT-UAB4-ZU7C2	QSMT-UASB-ZU8D2	ASMT-JAB4-ZV3H2	ASMT-JRB4-ZU802
ASMT-UAB4-ZU802	QSMT-URJ1-ZU802	QSMT-JAAE-ZU7C2	ASMT-JRB4-ZV302
ASMT-UAB4-ZU8C2	QSMT-URFB-ZU802	QSMT-JAAE-ZV2C2	QSMT-JRBG-ZV302
ASMT-UAB4-ZU7H2			

Group 2

ASMT-SAB4-YW905	ASMT-SAB4-ZX3C5	ASMT-SRB4-YW905	QSMT-SRAP-ZX305
ASMT-SAB4-YX305	ASMT-SAB4-ZX3E5	ASMT-SRB4-YX305	QSMT-SRRK-ZX305
ASMT-SAB4-ZW905	ASMT-SAB4-ZX3H5	ASMT-SRB4-ZW905	ASMT-SAA4-ZX3C5
ASMT-SAB4-ZW9C5	ASMT-SHB4-YX305	ASMT-SRB4-ZX305	ASMT-SAA4-ZX305
ASMT-SAB4-ZW9H5	ASMT-SHB4-ZX305	QSMT-SRDF-ZX305	ASMT-SAA4-ZX3J5
ASMT-SAB4-ZX305			

Description and Extent of Change:

Discontinue of current dice supply


Reasons for Change:

Assurance of supply



Effect of Change on Fit, Form, Function, Quality, or Reliability:

There will be no change on fit, form, quality and reliability of final product. Vf characteristic is slightly difference as illustrated below:



Effective Date of Change:

Parts with above change will commence 90 days after issuance date above. Broadcom will continue ship parts from both dice sources after implementation date until inventories of existing dice source are fully depleted.

Qualification Data:

No change in reliability performance. Product and qualification data will be available upon request.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.