


Product Change Notification (PCN)


PCN Number	502395	Date Issued	January 26, 2017
Reason for Change	Obsolete		
Change Type Description	This is to inform you that the part(s) referenced in this notice will be made obsolete due to low demand. Please contact your Molex Sales Engineer for additional questions concerning possible replacement part(s).		
Reason for Short Notice	Special Request		
Planned Implementation Date	August 07, 2017		
Recommended Replacement Parts	Please see the attached replacement parts list .xls file.		
Last Time Buy Date for Obsolete Parts	June 07, 2017		
Last Time Ship Date for Obsolete Parts	August 07, 2017		

Before Change

- Molex is making series 2145 and 7580 housings and assemblies obsolete. See attached document for affected assemblies and suggested replacement parts.



Series 7580 housing



Series 2145 assembly

After Change

Overview

- Molex is making series 2145 and 7580 housings and assemblies obsolete
 - The replacement parts are listed on the attached file.
 - The last buy date for the current parts is June 7, 2017
 - The last ship date for the current parts is August 7, 2017
- Part Number Impact
 - 2145 & 7580 series assemblies



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:502395**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Replacemant parts list

Molex Part Number	Replacement part number:	Replacement type
89003001	N/A	No replacement part
15040288	N/A	No replacement part
9463042	9484041	Replacement with differences
9521026	9481024	Drop in replacement
9521030	9481033	Drop in replacement
9521033	9484038	Replacement with differences
9521035	418150356	Replacement with differences
9521036	9481034	Drop in replacement
9521041	9481044	Replacement with differences
9521046	9481044	Drop in replacement
9521056	9481054	Drop in replacement
9521060	9481063	Drop in replacement
9521065	418150359	Replacement with differences
9521066	9481064	Drop in replacement
9521069	9482065	Replacement with differences
9521076	9481074	Drop in replacement
9521080	9481083	Drop in replacement
9521083	9484088	Replacement with differences
9521085	418150361	Replacement with differences
9521086	9481084	Drop in replacement
9521093	9484098	Replacement with differences
9521095	418150362	Replacement with differences
9521096	9481094	Drop in replacement
9521099	9482095	Replacement with differences
9521100	9481103	Drop in replacement
9521101	9481104	Replacement with differences
9521103	9484108	Replacement with differences
9521105	418150363	Replacement with differences
9521106	9481104	Drop in replacement
9521116	9481114	Drop in replacement
9521120	9481123	Drop in replacement
9521121	9481124	Replacement with differences
9521123	9484128	Replacement with differences
9521126	9481124	Drop in replacement
9521136	9481134	Drop in replacement
9521146	9481144	Drop in replacement
9521149	9482145	Replacement with differences
9521153	9484158	Replacement with differences
9521156	9481154	Drop in replacement
9521170	418150630	Drop in replacement
9522028	9484021	Replacement with differences
9522038	9484031	Replacement with differences

9522048	9484041	Replacement with differences
9522058	9484051	Replacement with differences
9522068	9484061	Replacement with differences
9522078	9484071	Replacement with differences
9522079	9482078	Drop in replacement
9522088	9484081	Replacement with differences
9522097	418150637	Replacement with differences
9522098	9484091	Replacement with differences
9522108	9484101	Replacement with differences
9522118	9484111	Replacement with differences
9522128	9484121	Replacement with differences
9522129	9482128	Drop in replacement
9522138	9484131	Replacement with differences
9522148	9484141	Replacement with differences
9522158	9484151	Replacement with differences
9522159	9482158	Drop in replacement
9523021	9482021	Drop in replacement
9523022	418150327	Replacement with differences
9523023	9482023	Drop in replacement
9523028	9482020	Drop in replacement
9523031	9482031	Drop in replacement
9523032	418150328	Replacement with differences
9523033	9482033	Drop in replacement
9523034	9482035	Drop in replacement
9523038	9482030	Drop in replacement
9523041	9482041	Drop in replacement
9523042	418150329	Replacement with differences
9523043	9482043	Drop in replacement
9523044	9482045	Drop in replacement
9523045	9481043	Replacement with differences
9523048	9482040	Drop in replacement
9523051	9482051	Drop in replacement
9523052	9482056	Replacement with differences
9523053	9482053	Drop in replacement
9523054	9482055	Drop in replacement
9523058	9482050	Drop in replacement
9523061	9482061	Drop in replacement
9523062	418150331	Replacement with differences
9523063	9482063	Drop in replacement
9523064	9482065	Drop in replacement
9523068	9482060	Drop in replacement
9523071	9482071	Drop in replacement
9523072	418150332	Replacement with differences
9523073	9482073	Drop in replacement
9523078	9482070	Drop in replacement
9523081	9482081	Drop in replacement
9523082	9482086	Replacement with differences

9523083	9482083	Drop in replacement
9523085	9481083	Replacement with differences
9523089	9482085	Drop in replacement
9523091	9482091	Drop in replacement
9523092	418150334	Replacement with differences
9523093	9482093	Drop in replacement
9523098	9482090	Drop in replacement
9523101	9482101	Drop in replacement
9523102	9482106	Replacement with differences
9523103	9482103	Drop in replacement
9523105	9481103	Replacement with differences
9523108	9482100	Drop in replacement
9523111	9482111	Drop in replacement
9523112	418150336	Replacement with differences
9523113	9482113	Drop in replacement
9523118	9482110	Drop in replacement
9523121	9482121	Drop in replacement
9523122	418150337	Replacement with differences
9523123	9482123	Drop in replacement
9523128	9482120	Drop in replacement
9523131	9482131	Drop in replacement
9523132	418150338	Replacement with differences
9523133	9482133	Drop in replacement
9523138	9482130	Drop in replacement
9523141	9482141	Drop in replacement
9523142	418150339	Replacement with differences
9523143	9482143	Drop in replacement
9523148	9482140	Drop in replacement
9523151	9482151	Drop in replacement
9523152	418150340	Replacement with differences
9523153	9482153	Drop in replacement
9523158	9482150	Drop in replacement
9525102	9482102	Drop in replacement
9525142	9482142	Drop in replacement
9533051	9482051	Replacement with differences
9533061	9482061	Replacement with differences
9533081	9482081	Replacement with differences
9533091	9482091	Replacement with differences
9533101	9482101	Replacement with differences
9533121	9482121	Replacement with differences
9533151	9482151	Replacement with differences
9623021	9483025	Drop in replacement
9623022	9483024	Replacement with differences
9623023	9483026	Drop in replacement
9623031	9483035	Drop in replacement
9623032	9483034	Replacement with differences
9623033	9483036	Drop in replacement

9623041	9483045	Drop in replacement
9623042	9483044	Replacement with differences
9623043	9483046	Drop in replacement
9623051	9483055	Drop in replacement
9623052	9483054	Replacement with differences
9623053	9483056	Drop in replacement
9623061	9483065	Drop in replacement
9623062	9483064	Replacement with differences
9623063	9483066	Drop in replacement
9623071	9483075	Drop in replacement
9623072	9483074	Replacement with differences
9623073	9483076	Drop in replacement
9623081	9483085	Drop in replacement
9623082	9483084	Replacement with differences
9623083	9483086	Drop in replacement
9623091	9483095	Drop in replacement
9623092	9483094	Replacement with differences
9623093	9483096	Drop in replacement
9623101	9483105	Drop in replacement
9623102	9483104	Replacement with differences
9623103	9483106	Drop in replacement
9623111	9483115	Drop in replacement
9623112	9483114	Replacement with differences
9623113	9483116	Drop in replacement
9623121	9483125	Drop in replacement
9623122	9483124	Replacement with differences
9623123	9483126	Drop in replacement
9623131	9483135	Drop in replacement
9623132	9483134	Replacement with differences
9623133	9483136	Drop in replacement
9623141	9483145	Drop in replacement
9623142	9483144	Replacement with differences
9623143	9483146	Drop in replacement
9623151	9483155	Drop in replacement
9623152	9483154	Replacement with differences
9623153	9483156	Drop in replacement
9624027	9485024	Drop in replacement
9624028	9485026	Replacement with differences
9624029	9485025	Drop in replacement
9624037	9485034	Drop in replacement
9624038	9485036	Replacement with differences
9624039	9485035	Drop in replacement
9624047	9485044	Drop in replacement
9624048	9485046	Replacement with differences
9624049	9485045	Drop in replacement
9624057	9485054	Drop in replacement
9624058	9485056	Replacement with differences

9624059	9485055	Drop in replacement
9624067	9485064	Drop in replacement
9624068	9485066	Replacement with differences
9624069	9485065	Drop in replacement
9624077	9485074	Drop in replacement
9624078	9485076	Replacement with differences
9624079	9485075	Drop in replacement
9624087	9485084	Drop in replacement
9624088	9485086	Replacement with differences
9624089	9485085	Drop in replacement
9624097	9485094	Drop in replacement
9624098	9485096	Replacement with differences
9624099	9485095	Drop in replacement
9624107	9485104	Drop in replacement
9624108	9485106	Replacement with differences
9624109	9485105	Drop in replacement
9624117	9485114	Drop in replacement
9624118	9485116	Replacement with differences
9624119	9485115	Drop in replacement
9624127	9485124	Drop in replacement
9624128	9485126	Replacement with differences
9624129	9485125	Drop in replacement
9624137	9485134	Drop in replacement
9624138	9485136	Replacement with differences
9624139	9485135	Drop in replacement
9624147	9485144	Drop in replacement
9624149	9485145	Drop in replacement
9624157	9485154	Drop in replacement
9624158	9485156	Replacement with differences
9624159	9485155	Drop in replacement
9626024	9484021	Drop in replacement
9626025	9484028	Drop in replacement
9626034	9484031	Drop in replacement
9626035	9484038	Drop in replacement
9626044	9484041	Drop in replacement
9626045	9484048	Drop in replacement
9626054	9484051	Drop in replacement
9626055	9484058	Drop in replacement
9626064	9484061	Drop in replacement
9626065	9484068	Drop in replacement
9626074	9484071	Drop in replacement
9626075	9484078	Drop in replacement
9626084	9484081	Drop in replacement
9626085	9484088	Drop in replacement
9626094	9484091	Drop in replacement
9626095	9484098	Drop in replacement
9626104	9484101	Drop in replacement

9626105	9484108	Drop in replacement
9626114	9484111	Drop in replacement
9626115	9484118	Drop in replacement
9626124	9484121	Drop in replacement
9626125	9484128	Drop in replacement
9626134	9484131	Drop in replacement
9626135	9484138	Drop in replacement
9626144	9484141	Drop in replacement
9626145	9484148	Drop in replacement
9626154	9484151	Drop in replacement
9626155	9484158	Drop in replacement
9863042	9484041	Replacement with differences
9863082	9484081	Replacement with differences
9863102	9484101	Replacement with differences
9863112	9484111	Replacement with differences
50290036	9481023	Drop in replacement
50290037	9481033	Drop in replacement
50290038	9481043	Drop in replacement
50290039	9481053	Drop in replacement
50290040	9481073	Drop in replacement
50290041	9481093	Drop in replacement
50290042	9481113	Drop in replacement
50290043	9481133	Drop in replacement
50290044	9481153	Drop in replacement
50291880	9482121	Drop in replacement
50304405	9484021	Drop in replacement
50304406	9484031	Drop in replacement
50304407	9484041	Drop in replacement
50304408	9484051	Drop in replacement
50304409	9484061	Drop in replacement
50304411	9484071	Drop in replacement
50304412	9484081	Drop in replacement
50304413	9484091	Drop in replacement
50304414	9484101	Drop in replacement
50304415	9484111	Drop in replacement
50304416	9484121	Drop in replacement
50304417	9484131	Drop in replacement
50304418	9484141	Drop in replacement
50304419	9484151	Drop in replacement

Option text if differences is choose	alt replacement
Replacment is white, has phos bronze terminals, 197 plating	
Replacement has phos bronze terminals instead of brass	
REPLACEMENT HAS HOOKS	
REPLACEMENT HAS PHOS BRONZE TERMINALS	
REPLACEMENT HAS HOOKS	
Replacement has .120 dimension C instead of .189	
Replacement has phos bronze terminals instead of brass	
REPLACEMENT HAS HOOKS	
Replacement has phos bronze terminals instead of brass	
REPLACEMENT HAS HOOKS	
Replacement has .120 dimension C instead of .189	
REPLACEMENT HAS PHOS BRONZE TERMINALS	
Replacement has phos bronze terminals instead of brass	
REPLACEMENT HAS HOOKS	
REPLACEMENT HAS PHOS BRONZE TERMINALS	
Replacement has phos bronze terminals instead of brass	
Replacement has .120 dimension C instead of .189	
Replacement has phos bronze terminals instead of brass	
Replacment has 197 plating instead of 909	
Replacment has 197 plating instead of 909	

Replacment has 197 plating instead of 909	
Replacment has 197 plating instead of 909	
Replacment has 197 plating instead of 909	
Replacment has 197 plating instead of 909	
Replacment has 197 plating instead of 909	
Replacement has phos bronze terminals and 197 plating	
Replacment has 197 plating instead of 909	
Replacment has 197 plating instead of 909	
Replacment has 197 plating instead of 909	
Replacment has 197 plating instead of 909	
Replacment has 197 plating instead of 909	
Replacment has 197 plating instead of 909	
Replacment has 197 plating instead of 909	
Replacement has no hooks, no ramp, alt replacment part is	9484021
Replacement has no hooks, no ramp	9484031
Replacement has no hooks, no ramp	9484041
Replacement has phos bronze terminals, 197 plating	
Replacement has no hooks, no ramp	9484051
Replacement has no hooks, no ramp	9484061
Replacement has no hooks, no ramp	9484071
Replacement has no hooks, no ramp	9484081

Replacement has phos bronze terminals, 197 plating	
Replacement has no hooks, no ramp	9484091
Replacement has no hooks, no ramp	9484101
Replacement has phos bronze terminals, 197 plating	
Replacement has no hooks, no ramp	9484111
Replacement has no hooks, no ramp	9484121
Replacement has no hooks, no ramp	9484131
Replacement has no hooks, no ramp	9484141
Replacement has no hooks, no ramp	9484151
Replacement has white housing	
Replacement has white housing	
Replacement has white housing	
Replacement has white housing	
Replacement has white housing	
Replacement has white housing	
Replacement has white housing	
Replacment has .125 dimension C instead of .160	
Replacment has .125 dimension C instead of .160	

