

Product Change Notice

PCN#: EE-PCN17050

12/06/2017

CLASSIFICATION OF CHANGE:

Material Change.

DESCRIPTION OF CHANGE:

Change 1) Remove the solderable MW82 180C rated wire and replace with non-solderable MW35 200C rated wire.
Change 2) Any color wire is permitted & both windings can have the same color.

REASON FOR CHANGE:

Improve wire insulation performance after IR reflow.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices. The higher rated magnet wire is considered an improvement.

PARTS FAMILIES AFFECTED:

CTX01-16373-R

TIME SCHEDULE:

Start Shipment Date: December 12, 2017

Last Time Buy Date: N/A

Last Time Shipment Date: N/A

SAMPLE AVAILABILITY:

Available upon request

ISSUED BY:

Global Product Manager: Steve Subiry

CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).