

### **Product Change Notification (PCN)**

PCN Number | 506449 Date Issued November 28, 2018

Reason for Change | Equipment Transfer, Production Transfer or Rearrangement

Change Type Description This letter is to inform you that production of the part(s) identified in this notice is being moved to a different production location. No

changes will be made to the product as a result of this move.

Reason for Short Notice | Special Request

Assessment of Change Product will be fully qualified before it is shipped. Qualification

reports are available upon request.

Internal Molex Qualification Date | January 01, 2019

Sample Availability Date (Changed Part) January 01, 2019

Planned Implementation Date | January 01, 2019

Method of Identifying Change Date code

#### After Change

- Change Content: 51441/54548/54550 Series manufacturing location change
- Change Reason: Because the capacity limited in Molex shanghai, the manufacturing location will be transfer to a new manufacturing location. But there are no change for the tooling and auto-assembly machines.
- Before change: Molex manufacturing location, Molex SH
- After change: Molex contract manufacturer, China.

The Molex contract manufacturer is an established ISO9001 plant and is already the home of many series PFC assembly products. This project will allow Molex to continue our tradition, provide the same quality products and improve our overall capacity.

 Detail schedule : Transfer beginning schedule: middle of Dec 2018
 Sample qualify and PPAP release schedule: middle of Feb 2019

Mass production schedule: middle of Mar 2019

Moles: Confidential Information

molex



## **Product Change Notification (PCN)**

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:506449" in the e-mail Subject line for faster response.

# RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com Molex Part #

#### **Part numbers affected:**

54548-0471	
54548-0671	
54548-1271	
54548-2071	