

End of Life Notification

From time to time we find it necessary to change, modify, or replace our product offering. These changes are usually the result of advancements in technology that offer improvements in performance or manufacturability. Unavailability of component parts, generally of an earlier technology or an older design, can cause the obsolescence of outdated product families.

We sincerely appreciate your business and will make every effort to work with you during your transition to the new power supplies. In some cases of obsolescence, a new advanced model has been introduced to replace the existing power supplies. All products now being discontinued are available for an end-of-life last time buy.

We have recommended a suitable replacement for your convenience on most of the end-of-life models. If you have any questions or need specific application assistance, please contact us (you may visit <https://www.artesyn.com/contact>. Email to productsupport.ep@Artesyn.com or call 1- 888-412-7832) or your local sales representative to assist you. Thank you for your continued patronage.

The following series/models have been marked as EOL:

Model No	Product Rank	Replacement Model	Replacement Info	LTB start	LTB end
uMP Dxx Dual Output Module Non-Iso	L		uMP IXX Dual Output Module Iso	07/01/2017	07/01/2018
uMP1C Case	L	uMP10		07/01/2017	07/01/2018
uMP1T Case	L	uMP10		07/01/2017	07/01/2018
uMP4C Case	L	uMP04		07/01/2017	07/01/2018
uMP4T Case	L	uMP04		07/01/2017	07/01/2018

[Click here to see more EOL information](#)