



## Product Change Notification

**PCN#: COPPER, OUTLETS, SURFACE RACEWAY- 2017-11-29      Issue Date: 2017-11-29**

**Impacted Regions:** NA EMEA LATAM AP

**Reason for Change:** Discontinuation Other

**DESCRIPTION OF CHANGE:** *(Not required for discontinuation)*

As a part of lifecycle management, the following parts are to be discontinued in all regions due to limited sales over the last three years. Parts affected include the PD Raceway Line, Floor Guard, and a Reduction in Faceplates.

- PD Raceway will be superceded by LDPH, a two piece hinged construction, power-rated raceway.
- Floor Guard will be discontinued with No Replacement
- Most faceplates affected will have a functional equivalent, however, some specialty faceplates will no longer be offered due to limited/no sales over the last three years.

**PHOTOS/DRAWING** *(where applicable)*

**IMPACTED PART NUMBERS AND REPLACEMENT (where applicable) PART NUMBERS:**

[Reference page 2/linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

Schedule for Change	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2017	11	29
Old product discontinuation date*	2018	4	04

**\*Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product discontinuation date.

**CUSTOMER SERVICE CONTACTS:**

<b>ASIA PACIFIC</b>	AUSTRALIA: 1-800 7263848 <a href="mailto:AUS-CustomerService@panduit.com">AUS-CustomerService@panduit.com</a>	CHINA: 800-820-1900 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	HONG KONG: 800-965768 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	
	INDIA: 000 800 6501844 (Fixed Line) 000 800 6500369 (Mobile) <a href="mailto:IND-customer_service@panduit.com">IND-customer_service@panduit.com</a>	INDONESIA: 001 803 65 7571 <a href="mailto:SGP-customer_service@panduit.com">SGP-customer_service@panduit.com</a>	JAPAN: +81-3-6863-6000 <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>	
	KOREA: 02-2182-7300 <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	MALAYSIA: 1800 801435 <a href="mailto:SGP-customer_service@panduit.com">SGP-customer_service@panduit.com</a>	SINGAPORE: 1-800-7263848 <a href="mailto:SGP-CUSTOMER_SERVICE@panduit.com">SGP-CUSTOMER_SERVICE@panduit.com</a>	
	TAIWAN: 0080 165 1487 <a href="mailto:SGP-CUSTOMER_SERVICE@panduit.com">SGP-CUSTOMER_SERVICE@panduit.com</a>	THAILAND: 001-800-65-6385 <a href="mailto:SGP-customer_service@panduit.com">SGP-customer_service@panduit.com</a>		
<b>LATIN AMERICA</b>	BRAZIL: 08000562613 (Toll Free) <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	MEXICO: +52-33-37776000, X80520 01 800 360 86 00 (Toll Free) <a href="mailto:mex-customerservice@panduit.com">mex-customerservice@panduit.com</a>	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>	
	<b>NORTH AMERICA</b>	USA & CANADA: 1-800-777-3300 <a href="mailto:cs@panduit.com">cs@panduit.com</a>	<b>EMEA</b> Phone:: +44 208 6017219 <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>	

To add a contact or to unsubscribe, please send an e-mail to [PCN@panduit.com](mailto:PCN@panduit.com)



IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
DJBXAW	No Replacement
FCFP2PAW-X	No Replacement
FP2DCEI	CP106EI-2G & CP1064EIY
FP2DCIW	CP106IW-2G & CP1064IWY
FP2DCWH	CP106WH-2G & CP1064WHY
FP2RCEI	CPGEI-2G & CFG4EI
FP2RCIW	CPGIW-2G & CFG4IW
FP2RCWH	CPGWH-2G & CFG4WH
JB1FSDEI-A	JB1DEI-A
JB1FSDIG-A	JB1DIG-A
JB1FSDIW-A	JB1DIW-A
JB1FSDWH-A	JB1DWH-A
JBX3510BL-A/N	No Replacement
PCF3EI-X	Functional Equivalent – LDPH3
PCF3IW-X	Functional Equivalent – LDPH3
PCF6EI-X	Functional Equivalent – LDPH5
PCF6IW-X	Functional Equivalent – LDPH5
PCPA10NSABL	No Replacement
PCPBRC	No Replacement
PCPECEI	No Replacement
PCPECIW	No Replacement
PCPNSATPWH/N	No Replacement
PD3EI6-A	Functional Equivalent – LDPH3
PD3IW6-A	Functional Equivalent – LDPH3
PD6EI6-A	Functional Equivalent – LDPH5
PD6IW6-A	Functional Equivalent – LDPH5
PDB36-A	Functional Equivalent – LDPH5
PDC3EI6	Functional Equivalent – LDPH3
PDC3IW6	Functional Equivalent – LDPH3
PDC6EI6	Functional Equivalent – LDPH5
PECF3EI-X	Functional Equivalent – LDPH3
PECF3IW-X	Functional Equivalent – LDPH3
PECF6EI-X	Functional Equivalent – LDPH5
PECF6IW-X	Functional Equivalent – LDPH5
PEEF36EI-X	Functional Equivalent – LDPH5
PEEF36IW-X	Functional Equivalent – LDPH5
PICF3EI-X	Functional Equivalent – LDPH3
PICF3IW-X	Functional Equivalent – LDPH3
PICF6EI-X	Functional Equivalent – LDPH5
PICF6IW-X	Functional Equivalent – LDPH5



POCF3EI-X	Functional Equivalent – LDPH3
POCF3IW-X	Functional Equivalent – LDPH3
POCF6EI-X	Functional Equivalent – LDPH5
POCF6IW-X	Functional Equivalent – LDPH5
PRAF3EI-X	Functional Equivalent – LDPH3
PRAF3IW-X	Functional Equivalent – LDPH3
PRAF6EI-X	Functional Equivalent – LDPH5
PRAF6IW-X	Functional Equivalent – LDPH5
PRJBX36EI	RJBX3510EI
PRJBX36IW	RJBX3510IW
PRJBX36WH	RJBX3510WH
PSJBXEI	No Replacement
PSJBXIW	No Replacement
PTF3EI-X	Functional Equivalent – LDPH3
PTF3IW-X	Functional Equivalent – LDPH3
PTF6EI-X	Functional Equivalent – LDPH5
PTF6IW-X	Functional Equivalent – LDPH5
RPCNSATPWH	No Replacement
T45CIG8	No Replacement
T702CPAW	No Replacement
T702TRLEI	Functional Equivalent – LDPH3
T702TRLWH	Functional Equivalent – LDPH3
T70B1AW	T70FV2AW
T70B1EI	T70FV2EI
T70B1IW	T70FV2IW
T70B1WH	T70FV2WH
T70B2EI	T70FV4EI
T70B2IW	T70FV4IW
T70B2WH	T70FV4WH
T70BBL2	No Replacement
T70BH1AW	T70FH2AW
T70BH1EI	T70FH2EI
T70BH1IW	T70FH2IW
T70BH1WH	T70FH2WH
T70BH2AW	T70FH4AW
T70BH2EI	T70FH4EI
T70BH2IW	T70FH4IW
T70BH2WH	T70FH4WH
T70BL1AW	No Replacement
T70BL1IW	No Replacement
T70BL2AW	No Replacement



T70BL2IW	No Replacement
T70L2EI	No Replacement
T70L2IW	No Replacement
T70L2WH	No Replacement
T70L4IW	No Replacement
T70L4WH	No Replacement
T70LV2IW	No Replacement
T70LV2WH	No Replacement
T70LV4IW	No Replacement
T70LV4WH	No Replacement
T70N2IW	No Replacement
T70N4IW	No Replacement
T70NV2IW	No Replacement
T70NV4IW	No Replacement
T70PIAL3IW	No Replacement
T70WCF2AW	No Replacement
T70WM40TREI	No Replacement
T70WM40TRIW	No Replacement
T70WM40TRWH	No Replacement
PC-435	No Replacement
FG1BR5.0-A	No Replacement
FG1EI5.0-A	No Replacement
FG1YL5.0-A	No Replacement
FG3BL5.0-A	No Replacement
FG3BL50.0-A	No Replacement
FG3BR5.0-A	No Replacement
FG3EI5.0-A	No Replacement
FG5BL5.0-A	No Replacement
FG5BR25.0-A	No Replacement
FG5EI25.0-A	No Replacement
FG5YL25.0-A	No Replacement