

PRODUCT DISCONTINUATION

#PD-AX-072F-11

Business Unit	Product Line Code	Type of Change	Action	Date of issue
AX	411	Discontinuation	Notify Distributors and Field	07/18/2011

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

The existing line of SMART mGuard variants are being replaced by a new line of SMART2 products utilizing updated firmware and a PCB board common across all mGuard product lines.

Warranty Information:

Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? N

Transaction Dates:

Last Buy from Phoenix Contact: 08/31/2011

Last Scheduled Ship from Phoenix Contact: 08/31/2011

PRODUCT DISCONTINUATION

Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

DAN SCHAFFER
Product Lead Specialist
(800)888-7388x3314
dschaffer@phoenixcon.com

Thank you,



Dan S Schaffer, Product Lead Specialist

Discontinued Part#	Type Description	Replacement Part#	Type Description
2700195	FL MGuard SMART/266	2700640	FL MGuard SMART2
2700181	FL MGuard SMART/533 VPN	2700639	FL MGuard SMART2 VPN
2700182	FL MGuard SMART/266 VPN	2700639	FL MGuard SMART2 VPN