



## Product Change Notice

Notice Number	2225
Date	December 8, 2022
Notification:	Product change notice
Description:	Discontinuation of the UBX series
Reason:	Low sales
Products affected:	UBX series parts
Last time buy date (LTB):	October 31, 2023
Last shipment date:	TBD (Subject to change due to manufacturing capacity and lead time. All orders must be approved by factory.)
Comments:	No replacements available

Sincerely,

Mark Gebbia,

Sales Application Engineering Manager – Americas

Part number	Part number	Part number
UBX1A102MHL	UBX1K101MHL	UBX2A470MPL1TD
UBX1A222MHL	UBX1K221MHL	UBX2A560MPL
UBX1A331MPL	UBX1K330MPL	UBX2A560MPL1TD
UBX1A331MPL1TD	UBX1K330MPL1TD	UBX2A680MHL
UBX1A332MHL	UBX1K331MHL	UBX2C100MPL
UBX1A471MPL	UBX1K470MPL	UBX2C100MPL1TD
UBX1A471MPL1TD	UBX1K470MPL1TD	UBX2C101MHL
UBX1A472MHL	UBX1K471MHL	UBX2C150MPL
UBX1C102MHL	UBX1K560MPL	UBX2C150MPL1TD
UBX1C221MPL	UBX1K560MPL1TD	UBX2C220MPL
UBX1C221MPL1TD	UBX1K680MPL	UBX2C220MPL1TD
UBX1C222MHL	UBX1K680MPL1TD	UBX2C330MHL
UBX1C331MPL	UBX1V010MPL	UBX2C470MHL
UBX1C331MPL1TD	UBX1V010MPL1TD	UBX2C560MHL
UBX1C332MHL	UBX1V100MPL	UBX2C680MHL
UBX1C471MHL	UBX1V100MPL1TD	UBX2D100MPL
UBX1E101MPL	UBX1V101MPL	UBX2D100MPL1TD
UBX1E101MPL1TD	UBX1V101MPL1TD	UBX2D100MPLAZO
UBX1E102MHL	UBX1V102MHL	UBX2D150MPL
UBX1E221MHL	UBX1V220MPL	UBX2D150MPL1TD
UBX1E331MHL	UBX1V220MPL1TD	UBX2D220MPL
UBX1E471MHL	UBX1V2R2MPL	UBX2D220MPL1TD
UBX1H101MPL	UBX1V2R2MPL1TD	UBX2D330MHL
UBX1H101MPL1TD	UBX1V330MPL	UBX2D560MHL
UBX1H102MHL	UBX1V330MPL1TD	UBX2D680MHL
UBX1H221MPL	UBX1V330MPLAZTTD	UBX2D6R8MPL
UBX1H221MPL1TD	UBX1V331MHL	UBX2D6R8MPL
UBX1H331MHL	UBX1V3R3MPL	UBX2D6R8MPL1TD
UBX1H471MHL	UBX1V3R3MPL1TD	UBX2G100MHL
UBX1H561MHL	UBX1V470MPL	UBX2G150MHL
UBX1H681MHL	UBX1V470MPL1TD	UBX2G3R3MPLAZOTD
UBX1J101MPL	UBX1V471MHL	UBX2G4R7MPL
UBX1J101MPL1TD	UBX1V4R7MPL	UBX2G4R7MPL1TD
UBX1J221MHL	UBX1V4R7MPL1TD	UBX2G6R8MHL
UBX1J331MHL	UBX2A101MHL	UBX2V100MHL
UBX1J471MHL	UBX2A220MPL	UBX2V150MHL
UBX1J560MPL	UBX2A220MPL1TD	UBX2V4R7MPL
UBX1J560MPL1TD	UBX2A221MHL	UBX2V4R7MPL1TD
UBX1J561MHL	UBX2A330MPL	UBX2V6R8MPL
UBX1J680MPL	UBX2A330MPL1TD	UBX2V6R8MPL1TD
UBX1J680MPL1TD	UBX2A331MHL	
UBX1J681MHL	UBX2A470MPL	

## PCN2225 Notification Acknowledgement

The indicated notification letter was received and acknowledged by the undersigned authority.

Company: \_\_\_\_\_

Location: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Name: \_\_\_\_\_

Signature: \_\_\_\_\_

Title: \_\_\_\_\_

Date: \_\_\_\_\_

We request you return a signed copy to our sales channels within 30 days of receipt of this notification. If we do not receive your acknowledgement by that date, we assume you agree and accept the preceding notification.