



Product Change Notice

Micron PCN: 30858
Date: 4/8/2013

Type of Change:	End of Life	
Title of Change:	Micron 32Mb-128Mb 90nm P5Q Serial PCM Discontinuance	
Description of Change:	90nm 32Mb-128Mb P5Q serial PCM is being discontinued due to optimization of manufacturing efficiency. There is no direct migration path. Customers should discuss potential migration options with their Micron sales representative.	
Reason for Change:	Optimization of Manufacturing Efficiency	
Contact Information:	<u>AMERICAS:</u> ARAVIND RAMAMOORTHY ARAMAMO@MICRON.COM	<u>EMEA:</u> MAURIZIO BELTRAMELLO MBELTRAMELLO@MICRON.COM
	<u>ASIA-PACIFIC:</u> JINGWEN YANG JYANG@MICRON.COM	<u>JAPAN:</u> DAIGO TOYAMA DTOYAMA@MICRON.COM

Product Affected: All 90nm P5Q products

Affected Micro Part Numbers

NP5Q032AE3ESFC0E	NP5Q128A13ESFC0E
NP5Q064AE3ESFC0E	NP5Q128AE3ESFC0E

Micron Sites Affected:	All Sites
Last Time Buy:	8-Oct-2013*
Last Time Ship:	8-Apr-2015

* Orders placed prior to the LTB date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.