

Light is OSRAM


Product or Individual Q-Code Discontinuation (acc. JEDEC J-STD-048)  
OS-PDN-2021-102-A

01 October 2021

---

Last order: 01 April 2022  
Last delivery: 01 October 2022

---



Please direct your feedback to your local Sales office.

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
LA H9PP	Q65111A7886	OSLON	No sufficient future volume forecast	LA H9PP	Q65111A4306	OSLON
KY DMLQ31.FY	Q65112A0271	SYNIOS	No sufficient future volume forecast	KY DMLQ31.FY	Q65113A3521	SYNIOS
KY DMLQ31.FY	Q65112A1323	SYNIOS	No sufficient future volume forecast	KY DMLQ31.FY	Q65113A3521	SYNIOS
KY DMLQ31.FY	Q65112A1338	SYNIOS	No sufficient future volume forecast	KY DMLQ31.FY	Q65113A3521	SYNIOS
KY DMLQ31.FY	Q65112A1434	SYNIOS	No sufficient future volume forecast	KY DMLQ31.FY	Q65113A3521	SYNIOS
KY DMLN31.FY	Q65112A2705	SYNIOS	No sufficient future volume forecast	KY DMLN31.FY	Q65111A6199	SYNIOS
KW HJL531.TE	Q65112A2862	OSLON	No sufficient future volume forecast	KW HJL531.TE	Q65112A8332	OSLON
KW H4L531.TE	Q65112A3246	OSLON	No sufficient future volume forecast	KW H4L531.TE	Q65112A4050	OSLON
KW H4L531.TE	Q65112A3252	OSLON	No sufficient future volume forecast	KW H4L531.TE	Q65112A4050	OSLON
KW HJL531.TE	Q65112A4181	OSLON	No sufficient future volume forecast	KW HJL531.TE	Q65112A8332	OSLON
KW H4L531.TE	Q65112A4825	OSLON	No sufficient future volume forecast	KW H4L531.TE	Q65112A6719	OSLON
KW H4L531.TE	Q65112A4833	OSLON	No sufficient future volume forecast	KW H4L531.TE	Q65112A6719	OSLON
KW HJL531.TE	Q65112A6275	OSLON	No sufficient future volume forecast	KW HJL531.TE	Q65112A8332	OSLON
KW HJL531.TE	Q65112A6602	OSLON	No sufficient future volume forecast	KW HJL531.TE	Q65112A8332	OSLON
KW HKL531.TE	Q65112A6893	OSLON	No sufficient future volume forecast	KW HKL531.TE	Q65112A8333	OSLON
KW HJL531.TE	Q65112A6894	OSLON	No sufficient future volume forecast	KW HJL531.TE	Q65112A8332	OSLON
KW HKL531.TE	Q65112A6971	OSLON	No sufficient future volume forecast	KW HKL531.TE	Q65112A8333	OSLON
LA E67F	Q65112A8057	Power TOPLED	No sufficient future volume forecast	LA E67F	Q65112A2777	Power TOPLED
KW H4L531.TE	Q65112A8095	OSLON	No sufficient future volume forecast	KW H4L531.TE	Q65112A4050	OSLON
KW H4L531.TE	Q65112A8096	OSLON	No sufficient future volume forecast	KW H4L531.TE	Q65112A4050	OSLON
KY DMLQ31.FY	Q65112A8696	SYNIOS	No sufficient future volume forecast	KY DMLQ31.FY	Q65113A3521	SYNIOS
KW HJL531.TE	Q65112A8853	OSLON	No sufficient future volume forecast	KW HJL531.TE	Q65112A8332	OSLON

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
KW HJL531.TE	Q65112A9017	OSLON	No sufficient future volume forecast	KW HJL531.TE	Q65112A8332	OSLON
LR G6SP	Q65113A1294	Advanced Power TOPLED	No sufficient future volume forecast	LR G6SP	Q65112A7545	Advanced Power TOPLED
LS E67F	Q65113A2316	Power TOPLED	No sufficient future volume forecast	LS E67F	Q65113A3071	Power TOPLED
LA E67F	Q65113A2401	Power TOPLED	No sufficient future volume forecast	LA E67F	Q65113A2588	Power TOPLED

Ordering Code	Product Descr.	Repl. Product Descr.	Repl. Ordering Code
Q65111A7886	LA H9PP-CXCZ-1-1+JZKY-24-1-A-R18-Z-KO	LA H9PP-JXKX-24-1-350-R18-Z	Q65111A4306
Q65112A0271	KY DMLQ31.FY-5JF7JF-5F-1-300-R18-HE	KY DMLQ31.FY-Z7JF11-5F-8E8G-300-R18	Q65113A3521
Q65112A1323	KY DMLQ31.FY-5JF7JF-5F-8E8G-300-R18-LM	KY DMLQ31.FY-Z7JF11-5F-8E8G-300-R18	Q65113A3521
Q65112A1338	KY DMLQ31.FY-8HF6JF-5F-8E8G-300-R18-XX	KY DMLQ31.FY-Z7JF11-5F-8E8G-300-R18	Q65113A3521
Q65112A1434	KY DMLQ31.FY-5JF8J-5F-8E8G-300-R18	KY DMLQ31.FY-Z7JF11-5F-8E8G-300-R18	Q65113A3521
Q65112A2705	KY DMLN31.FY-8G5H-5F-8E8G-150-R18-HE	KY DMLN31.FY-7G7H-5F-8E8G-150-R18	Q65111A6199
Q65112A2862	KW HJL531.TE-7Q5R-fcbB46-DFGF-NAL	KW HJL531.TE-T0T8-ebvFfcbB46-DFYF-A00-S	Q65112A8332
Q65112A3246	KW H4L531.TE-6R-fcdD46fcfF46-4LZL-ZKW	KW H4L531.TE-Z6R6-ebvFfcbB46-4LZL	Q65112A4050
Q65112A3252	KW H4L531.TE-6R-ebzB46fcbB46-4LZL-ZKW	KW H4L531.TE-Z6R6-ebvFfcbB46-4LZL	Q65112A4050
Q65112A4181	KW HJL531.TE-7Q5R-ebxD46ebzB46-DFYF-NAL	KW HJL531.TE-T0T8-ebvFfcbB46-DFYF-A00-S	Q65112A8332
Q65112A4825	KW H4L531.TE-7R-fcdD46fcfF46-4LZL-ZKW	KW H4L531.TE-Z6RF6-ebvFfcbB46-4LZL	Q65112A6719
Q65112A4833	KW H4L531.TE-7R-ebzB46fcbB46-4LZL-ZKW	KW H4L531.TE-Z6RF6-ebvFfcbB46-4LZL	Q65112A6719
Q65112A6275	KW HJL531.TE-7QF3-ebxD46ebzB46-DFGF-NAL	KW HJL531.TE-T0T8-ebvFfcbB46-DFYF-A00-S	Q65112A8332
Q65112A6602	KW HJL531.TE-D9T2-ebxD46ebzB46-DFYF-NAL	KW HJL531.TE-T0T8-ebvFfcbB46-DFYF-A00-S	Q65112A8332
Q65112A6893	KW HKL531.TE-8Q7R-ebvF46fcbB46-4LZL-KO	KW HKL531.TE-FOF8-ebvFfcbB46-4LZL-A00-S	Q65112A8333
Q65112A6894	KW HJL531.TE-Z6Q7-ebvFfcbB46-DFYF-KO	KW HJL531.TE-T0T8-ebvFfcbB46-DFYF-A00-S	Q65112A8332
Q65112A6971	KW HKL531.TE-6RF3-ebxD46ebzB46-4LQL-NAL	KW HKL531.TE-FOF8-ebvFfcbB46-4LZL-A00-S	Q65112A8333
Q65112A8057	LA E67F-BBCB-23-1-50-R18-Z-XX	LA E67F-BBCB-23-1-50-R18-Z	Q65112A2777
Q65112A8095	KW H4L531.TE-6R3-ebzB46fcbB46-4LZL-S-ZKW	KW H4L531.TE-Z6R6-ebvFfcbB46-4LZL	Q65112A4050
Q65112A8096	KW H4L531.TE-6R3-fcdD46fcfF46-4LZL-S-ZKW	KW H4L531.TE-Z6R6-ebvFfcbB46-4LZL	Q65112A4050
Q65112A8696	KY DMLQ31.FY-Z5JF5-5F-8E8G-300-S-XX	KY DMLQ31.FY-Z7JF11-5F-8E8G-300-R18	Q65113A3521
Q65112A8853	KW HJL531.TE-8Q3-ebxD46ebzB46-DFYF-NAL	KW HJL531.TE-T0T8-ebvFfcbB46-DFYF-A00-S	Q65112A8332
Q65112A9017	KW HJL531.TE-8Q3-ebxDebzB46-DFGF-A-S-NAL	KW HJL531.TE-T0T8-ebvFfcbB46-DFYF-A00-S	Q65112A8332
Q65113A1294	LR G6SP-DB-1-3A4B-140-R18-KO	LR G6SP-DA3EA3-1-3A4B-140-R18-Z-KO	Q65112A7545
Q65113A2316	LS E67F-ABCA-68-3A4B-50-R18	LS E67F-ABCB-68-3A4B-50-R18	Q65113A3071
Q65113A2401	LA E67F-BBCB-34-3A5A-50-R18-APS	LA E67F-CACB-34-3A5A-50-R18-Z-APS	Q65113A2588