

PRODUCT CHANGE NOTIFICATION

Product Category FIBER DISTRIBUTION 20221102-2

Product Group CONNECTIVITY & PATHWAYS

ISSUE DATE: 2-Nov-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Some Fiber Distribution products will be discontinued. Thanks for your ongoing support.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	11	2
Old product discontinuation date*	2023	1	31

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Discontinuation Date
FAP12WNKDBLLCZ	Direct	FAP12WABLBLDLCZ	31-Jan-23
FAP12WNKDBULCZ	No Replacement	NO-REPLACEMENT	31-Jan-23
FAP12WNKDDBLCZ	Direct	FAP12WFDBDBDLCZ	31-Jan-23
FAP12WNKDGRLCZ	Direct	FAP12WCGRGRDLCZ	31-Jan-23
FAP12WNKDIGLCZ	No Replacement	NO-REPLACEMENT	31-Jan-23
FAP12WNKDORLCZ	Direct	FAP12WEORORDLCZ	31-Jan-23
FAP12WNKDRDLCZ	Direct	FAP12WBRDRDDLCZ	31-Jan-23
FAP12WNKDSBLCZ	No Replacement	NO-REPLACEMENT	31-Jan-23
FAP12WNKDVLLCZ	No Replacement	NO-REPLACEMENT	31-Jan-23
FAP12WNKDYLLCZ	Direct	FAP12WDYLYLDLCZ	31-Jan-23