



## Product Discontinuation

### PDN-PCC-485-2017

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
PCC - PCB Connectors	AAY	Product Discontinuation	Notify Distributors and Field	3/22/2017

*Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.*

#### Description for Product Discontinuation

The following Basicline product families will be discontinued:

- BCA - angled terminal blocks
- BCVP - vertical plugs
- BCDH - horizontal, double row headers

Suggested replacement parts are already available for many of these items. All others are available upon request. Please refer the following list and the attachment.

#### Stock Status

- Can existing stock still be used?
- Is mixture of stock acceptable?

#### Transaction Dates

Last Buy from Phoenix Contact:	6/29/2018
Last Scheduled Ship from Phoenix Contact:	12/31/2018

Phoenix Contact Inc.  
P.O. BOX 4100  
Harrisburg, PA 17111-0100  
Phone: 717-944-1300  
Fax: 717-944-1625


## Product Discontinuation

Previous Product	New Product
	
	



Phoenix Contact Inc.  
P.O. BOX 4100  
Harrisburg, PA 17111-0100  
Phone: 717-944-1300  
Fax: 717-944-1625

## Product Discontinuation



*Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.*

**Contact Info:**

Harold McKee  
hmckee@phoenixcon.com

Thank you,

---

James Dunbar

Product Marketing Manager PCC



Phoenix Contact Inc.  
P.O. BOX 4100  
Harrisburg, PA 17111-0100  
Phone: 717-944-1300  
Fax: 717-944-1625

## Product Discontinuation

Discontinued Part #	Type Description	Replacement Part #	Type Description
5451734	BCVP-508WF-14 GN	1835025	MVSTBW 2,5/14-STF-5,08
5440693	BCVP-508WF-14 GY		
5440703	BCVP-508WF-15 GY		
5451750	BCVP-508WF-16 GN	1835041	MVSTBW 2,5/16-STF-5,08
5440716	BCVP-508WF-16 GY		
5440729	BCVP-508WF-17 GY		
5451792	BCVP-508WF-20 GN	1835083	MVSTBW 2,5/20-STF-5,08
5442989	BCDH-500H- 2 GN	1762046	MDSTB 2,5/ 2-G
5442992	BCDH-500H- 3 GN	1762059	MDSTB 2,5/ 3-G
5443001	BCDH-500H- 4 GN	1846386	MDSTB 2,5/ 4-G
5436924	BCDH-500H- 4 GY		
5443014	BCDH-500H- 5 GN	1837133	MDSTB 2,5/ 5-G
5436937	BCDH-500H- 5 GY		
5443043	BCDH-500H- 8 GN	1846425	MDSTB 2,5/ 8-G
5436979	BCDH-500H- 9 GY		
5452678	BCDH-500HS- 4 BK		
5452679	BCDH-500HS- 5 BK		
5443276	BCDH-500HS- 9 GN	1846580	MDSTBA 2,5/ 9-G
5443289	BCDH-500HS-10 GN	1846593	MDSTBA 2,5/10-G
5452643	BCDH-508H- 2 BK	1762091	MDSTB 2,5/ 2-G-5,08 BK
5443315	BCDH-508H- 2 GN	1762062	MDSTB 2,5/ 2-G-5,08
5437017	BCDH-508H- 2 GY		
5443328	BCDH-508H- 3 GN	1762075	MDSTB 2,5/ 3-G-5,08
5437020	BCDH-508H- 3 GY		
5443331	BCDH-508H- 4 GN	1842539	MDSTB 2,5/ 4-G-5,08
5437033	BCDH-508H- 4 GY		
5443344	BCDH-508H- 5 GN	1842542	MDSTB 2,5/ 5-G-5,08
5443357	BCDH-508H- 6 GN	1844977	MDSTB 2,5/ 6-G-5,08
5452648	BCDH-508H- 7 BK		
5443373	BCDH-508H- 8 GN	1840052	MDSTB 2,5/ 8-G-5,08
5437075	BCDH-508H- 8 GY	1765357	MDSTB 2,5/ 8-G-5,08 GY
5443399	BCDH-508H-10 GN	1842597	MDSTB 2,5/10-G-5,08
5437091	BCDH-508H-10 GY		
5443412	BCDH-508H-12 GN	1842610	MDSTB 2,5/12-G-5,08
5437457	BCDH-508HS- 2 GY		
5443548	BCDH-508HS- 3 GN	1842076	MDSTBA 2,5/ 3-G-5,08
5437460	BCDH-508HS- 3 GY		
5443551	BCDH-508HS- 4 GN	1842089	MDSTBA 2,5/ 4-G-5,08
5437473	BCDH-508HS- 4 GY		
5443564	BCDH-508HS- 5 GN	1842092	MDSTBA 2,5/ 5-G-5,08
5443577	BCDH-508HS- 6 GN	1842102	MDSTBA 2,5/ 6-G-5,08
5443593	BCDH-508HS- 8 GN	1842128	MDSTBA 2,5/ 8-G-5,08
5443616	BCDH-508HS-10 GN	1842144	MDSTBA 2,5/10-G-5,08
5440761	BCA-500X15- 2 GY		
5442167	BCA-500X15- 3 GN	1733428	SMKDSP 1,5/ 3
5440774	BCA-500X15- 3 GY		
5442154	BCA-500X15- 2 GN	1733415	SMKDSP 1,5/ 2
5442921	BCA-500X18- 2 GN	1713024	SMKDS 3/ 2
5436869	BCA-500X18- 2 GY		
5442934	BCA-500X18- 3 GN	1713037	SMKDS 3/ 3



## Product Discontinuation

5436872	BCA-500X18- 3 GY		
5430092	BCA-500X18- 5 BK		
5430139	BCA-500X18-11 BK		
5452002	BCA-508X15- 2 BK	1906459	SMKDSP 1,5/ 2-5,08 BK
5442947	BCA-508X15- 2 GN	1733570	SMKDSP 1,5/ 2-5,08
5440910	BCA-508X15- 2 GY	1730764	SMKDSP 1,5/ 2-5,08 GY
5452003	BCA-508X15- 3 BK	1717981	SMKDSP 1,5/ 3-5,08 BK
5442950	BCA-508X15- 3 GN	1733583	SMKDSP 1,5/ 3-5,08
5440923	BCA-508X15- 3 GY	1730777	SMKDSP 1,5/ 3-5,08 GY
5440949	BCA-508X15- 5 GY		
5442963	BCA-508X18- 2 GN	1713723	SMKDS 3/ 2-5,08
5436885	BCA-508X18- 2 GY		
5442976	BCA-508X18- 3 GN	1713736	SMKDS 3/ 3-5,08
5436898	BCA-508X18- 3 GY	1871254	SMKDS 3/ 3-5,08 GY
5449005	BCVP-350R- 2 GN	1863152	MCVR 1,5/ 2-ST-3,5
5452699	BCVP-350R- 3 BK		
5449018	BCVP-350R- 3 GN	1863165	MCVR 1,5/ 3-ST-3,5
5437570	BCVP-350R- 3 GY		
5452700	BCVP-350R- 4 BK		
5441472	BCVP-350R- 4 GN	1863178	MCVR 1,5/ 4-ST-3,5
5452701	BCVP-350R- 5 BK		
5449021	BCVP-350R- 5 GN	1863181	MCVR 1,5/ 5-ST-3,5
5441485	BCVP-350R- 6 GN	1863194	MCVR 1,5/ 6-ST-3,5
5437606	BCVP-350R- 6 GY		
5449034	BCVP-350R- 7 GN	1863204	MCVR 1,5/ 7-ST-3,5
5452704	BCVP-350R- 8 BK		
5449047	BCVP-350R- 8 GN	1863217	MCVR 1,5/ 8-ST-3,5
5437622	BCVP-350R- 8 GY		
5449050	BCVP-350R- 9 GN	1863220	MCVR 1,5/ 9-ST-3,5
5449063	BCVP-350R-10 GN	1863233	MCVR 1,5/10-ST-3,5
5437648	BCVP-350R-10 GY		
5452707	BCVP-350R-11 BK		
5449076	BCVP-350R-11 GN	1863246	MCVR 1,5/11-ST-3,5
5449089	BCVP-350R-12 GN	1863259	MCVR 1,5/12-ST-3,5
5437664	BCVP-350R-12 GY		
5452712	BCVP-350R-16 BK		
5437703	BCVP-350R-16 GY		
5438401	BCVP-350RF- 2 GY		
5438427	BCVP-350RF- 4 GY		
5438443	BCVP-350RF- 6 GY		
5438456	BCVP-350RF- 7 GY		
5449199	BCVP-350RF- 8 GN	1863369	MCVR 1,5/ 8-STF-3,5
5438469	BCVP-350RF- 8 GY		
5441414	BCVP-350W- 2 GN	1862852	MCVW 1,5/ 2-ST-3,5
5439167	BCVP-350W- 2 GY		
5441427	BCVP-350W- 3 GN	1862865	MCVW 1,5/ 3-ST-3,5
5439170	BCVP-350W- 3 GY		
5441430	BCVP-350W- 4 GN	1862878	MCVW 1,5/ 4-ST-3,5
5439183	BCVP-350W- 4 GY		
5441443	BCVP-350W- 5 GN	1862881	MCVW 1,5/ 5-ST-3,5
5452591	BCVP-350W- 6 BK		



Phoenix Contact Inc.  
P.O. BOX 4100  
Harrisburg, PA 17111-0100  
Phone: 717-944-1300  
Fax: 717-944-1625

## Product Discontinuation

5449283	BCVP-350W- 6 GN	1862894	MCVW 1,5/ 6-ST-3,5
5439206	BCVP-350W- 6 GY		
5449296	BCVP-350W- 7 GN	1862904	MCVW 1,5/ 7-ST-3,5
5441456	BCVP-350W- 8 GN	1862917	MCVW 1,5/ 8-ST-3,5
5441469	BCVP-350W- 9 GN	1862920	MCVW 1,5/ 9-ST-3,5
5449306	BCVP-350W-10 GN	1862933	MCVW 1,5/10-ST-3,5
5439251	BCVP-350W-11 GY		
5449322	BCVP-350W-12 GN	1862959	MCVW 1,5/12-ST-3,5
5439264	BCVP-350W-12 GY		
5439280	BCVP-350W-14 GY		
5440017	BCVP-350WF- 3 GY		
5440020	BCVP-350WF- 4 GY		
5440046	BCVP-350WF- 6 GY		
5440088	BCVP-350WF-10 GY		
5452713	BCVP-381R- 2 BK	1903067	MCVR 1,5/ 2-ST-3,81 BK
5449526	BCVP-381R- 2 GN	1827127	MCVR 1,5/ 2-ST-3,81
5437758	BCVP-381R- 2 GY		
5452714	BCVP-381R- 3 BK	1859700	MCVR 1,5/ 3-ST-3,81 BK
5449539	BCVP-381R- 3 GN	1827130	MCVR 1,5/ 3-ST-3,81
5437761	BCVP-381R- 3 GY		
5452715	BCVP-381R- 4 BK	1896417	MCVR 1,5/ 4-ST-3,81 BK
5449542	BCVP-381R- 4 GN	1827143	MCVR 1,5/ 4-ST-3,81
5437774	BCVP-381R- 4 GY		
5452716	BCVP-381R- 5 BK	1903070	MCVR 1,5/ 5-ST-3,81 BK
5449555	BCVP-381R- 5 GN	1827156	MCVR 1,5/ 5-ST-3,81
5452717	BCVP-381R- 6 BK	1903083	MCVR 1,5/ 6-ST-3,81 BK
5449568	BCVP-381R- 6 GN	1827169	MCVR 1,5/ 6-ST-3,81
5437790	BCVP-381R- 6 GY		
5449571	BCVP-381R- 7 GN	1827172	MCVR 1,5/ 7-ST-3,81
5437800	BCVP-381R- 7 GY		
5452719	BCVP-381R- 8 BK	1800222	MCVR 1,5/ 8-ST-3,81 BK
5449584	BCVP-381R- 8 GN	1827185	MCVR 1,5/ 8-ST-3,81
5452720	BCVP-381R- 9 BK	1800224	MCVR 1,5/ 9-ST-3,81 BK
5449597	BCVP-381R- 9 GN	1827198	MCVR 1,5/ 9-ST-3,81
5437826	BCVP-381R- 9 GY		
5449607	BCVP-381R-10 GN	1827208	MCVR 1,5/10-ST-3,81
5449610	BCVP-381R-11 GN	1827211	MCVR 1,5/11-ST-3,81
5437842	BCVP-381R-11 GY		
5449623	BCVP-381R-12 GN	1827224	MCVR 1,5/12-ST-3,81
5437855	BCVP-381R-12 GY		
5437868	BCVP-381R-13 GY		
5449649	BCVP-381R-14 GN	1827240	MCVR 1,5/14-ST-3,81
5437871	BCVP-381R-14 GY		
5437897	BCVP-381R-16 GY		
5449678	BCVP-381RF- 2 GN	1828346	MCVR 1,5/ 2-STF-3,81
5438595	BCVP-381RF- 2 GY		
5449681	BCVP-381RF- 3 GN	1828359	MCVR 1,5/ 3-STF-3,81
5438605	BCVP-381RF- 3 GY		
5438618	BCVP-381RF- 4 GY		
5449717	BCVP-381RF- 6 GN	1828388	MCVR 1,5/ 6-STF-3,81
5438634	BCVP-381RF- 6 GY		



Phoenix Contact Inc.  
P.O. BOX 4100  
Harrisburg, PA 17111-0100  
Phone: 717-944-1300  
Fax: 717-944-1625

## Product Discontinuation

5449733	BCVP-381RF- 8 GN	1828401	MCVR 1,5/ 8-STF-3,81
5438650	BCVP-381RF- 8 GY		
5438663	BCVP-381RF- 9 GY		
5449759	BCVP-381RF-10 GN	1828427	MCVR 1,5/10-STF-3,81
5438676	BCVP-381RF-10 GY		
5438715	BCVP-381RF-14 GY		
5449827	BCVP-381W- 2 GN	1826979	MCVW 1,5/ 2-ST-3,81
5439358	BCVP-381W- 2 GY		
5449830	BCVP-381W- 3 GN	1826982	MCVW 1,5/ 3-ST-3,81
5439361	BCVP-381W- 3 GY		
5449843	BCVP-381W- 4 GN	1826995	MCVW 1,5/ 4-ST-3,81
5439374	BCVP-381W- 4 GY		
5449856	BCVP-381W- 5 GN	1827004	MCVW 1,5/ 5-ST-3,81
5449869	BCVP-381W- 6 GN	1827017	MCVW 1,5/ 6-ST-3,81
5439390	BCVP-381W- 6 GY		
5449872	BCVP-381W- 7 GN	1827020	MCVW 1,5/ 7-ST-3,81
5439400	BCVP-381W- 7 GY		
5449885	BCVP-381W- 8 GN	1827033	MCVW 1,5/ 8-ST-3,81
5452849	BCVP-381W- 9 BK	1800252	MCVW 1,5/ 9-ST-3,81 BK
5449898	BCVP-381W- 9 GN	1827046	MCVW 1,5/ 9-ST-3,81
5449908	BCVP-381W-10 GN	1827059	MCVW 1,5/10-ST-3,81
5439439	BCVP-381W-10 GY		
5449924	BCVP-381W-12 GN	1827075	MCVW 1,5/12-ST-3,81
5439455	BCVP-381W-12 GY		
5449940	BCVP-381W-14 GN	1827091	MCVW 1,5/14-ST-3,81
5439497	BCVP-381W-16 GY		
5440208	BCVP-381WF- 3 GY		
5440224	BCVP-381WF- 5 GY		
5440240	BCVP-381WF- 7 GY		
5440253	BCVP-381WF- 8 GY		
5450078	BCVP-381WF-12 GN	1828595	MCVW 1,5/12-STF-3,81
5450117	BCVP-381WF-16 GN	1828634	MCVW 1,5/16-STF-3,81
5450120	BCVP-500R- 2 GN	1792016	MVSTBR 2,5/ 2-ST
5452729	BCVP-500R- 3 BK	1740411	MVSTBR 2,5/ 3-ST BK
5450133	BCVP-500R- 3 GN	1792029	MVSTBR 2,5/ 3-ST
5437952	BCVP-500R- 3 GY	1877892	MVSTBR 2,5/ 3-ST GY
5452730	BCVP-500R- 4 BK	1740628	MVSTBR 2,5/ 4-ST BK
5450146	BCVP-500R- 4 GN	1792032	MVSTBR 2,5/ 4-ST
5452731	BCVP-500R- 5 BK	1746567	MVSTBR 2,5/ 5-ST BK
5450159	BCVP-500R- 5 GN	1792045	MVSTBR 2,5/ 5-ST
5452732	BCVP-500R- 6 BK	1740615	MVSTBR 2,5/ 6-ST BK
5450162	BCVP-500R- 6 GN	1792058	MVSTBR 2,5/ 6-ST
5437981	BCVP-500R- 6 GY		
5450175	BCVP-500R- 7 GN	1792061	MVSTBR 2,5/ 7-ST
5437994	BCVP-500R- 7 GY		
5452734	BCVP-500R- 8 BK		
5450188	BCVP-500R- 8 GN	1792074	MVSTBR 2,5/ 8-ST
5450191	BCVP-500R- 9 GN	1792087	MVSTBR 2,5/ 9-ST
5450201	BCVP-500R-10 GN	1792090	MVSTBR 2,5/10-ST
5438032	BCVP-500R-11 GY		
5450227	BCVP-500R-12 GN	1792113	MVSTBR 2,5/12-ST





Phoenix Contact Inc.  
P.O. BOX 4100  
Harrisburg, PA 17111-0100  
Phone: 717-944-1300  
Fax: 717-944-1625

## Product Discontinuation

5438045	BCVP-500R-12 GY		
5450230	BCVP-500R-13 GN	1792126	MVSTBR 2,5/13-ST
5450243	BCVP-500R-14 GN	1792139	MVSTBR 2,5/14-ST
5450256	BCVP-500R-15 GN	1792142	MVSTBR 2,5/15-ST
5450269	BCVP-500R-16 GN	1792155	MVSTBR 2,5/16-ST
5450272	BCVP-500R-17 GN	1792168	MVSTBR 2,5/17-ST
5438100	BCVP-500R-18 GY	1874879	MVSTBR 2,5/18-ST GY
5438168	BCVP-500R-24 GY		
5450353	BCVP-500RF- 2 GN	1835478	MVSTBR 2,5/ 2-STF
5438922	BCVP-500RF-16 GY		
5441825	BCVP-500W- 2 BK VPE500		
5441838	BCVP-500W- 3 BK VPE500		
5450557	BCVP-500W- 3 GN	1792537	MVSTBW 2,5/ 3-ST
5441841	BCVP-500W- 4 BK VPE500		
5450560	BCVP-500W- 4 GN	1792540	MVSTBW 2,5/ 4-ST
5450573	BCVP-500W- 5 GN	1792553	MVSTBW 2,5/ 5-ST
5439578	BCVP-500W- 5 GY		
5441854	BCVP-500W- 6 BK VPE500		
5450586	BCVP-500W- 6 GN	1792566	MVSTBW 2,5/ 6-ST
5455811	BCVP-500W- 6 GNBD		
5452863	BCVP-500W- 8 BK	1877915	MVSTBW 2,5/ 8-ST BK
5450609	BCVP-500W- 8 GN	1792582	MVSTBW 2,5/ 8-ST
5452865	BCVP-500W-10 BK	1740741	MVSTBW 2,5/10-ST BK
5450625	BCVP-500W-10 GN	1792605	MVSTBW 2,5/10-ST
5452867	BCVP-500W-12 BK		
5450641	BCVP-500W-12 GN	1792621	MVSTBW 2,5/12-ST
5450654	BCVP-500W-13 GN	1792634	MVSTBW 2,5/13-ST
5450683	BCVP-500W-16 GN	1792663	MVSTBW 2,5/16-ST
5439688	BCVP-500W-16 GY		
5452875	BCVP-500W-20 BK		
5450764	BCVP-500W-24 GN	1792744	MVSTBW 2,5/24-ST
5450780	BCVP-500WF- 3 GN	1835290	MVSTBW 2,5/ 3-STF
5450793	BCVP-500WF- 4 GN	1835300	MVSTBW 2,5/ 4-STF
5440525	BCVP-500WF-16 GY		
5452751	BCVP-508R- 2 BK	1740903	MVSTBR 2,5/ 2-ST-5,08 BK
5450968	BCVP-508R- 2 GN	1792249	MVSTBR 2,5/ 2-ST-5,08
5454951	BCVP-508R- 2 GY BD:NZ1		
5452752	BCVP-508R- 3 BK	1783708	MVSTBR 2,5/ 3-ST-5,08 BK
5450971	BCVP-508R- 3 GN	1792252	MVSTBR 2,5/ 3-ST-5,08
5438184	BCVP-508R- 3 GY	1765111	MVSTBR 2,5/ 3-ST-5,08 GY
5452753	BCVP-508R- 4 BK	1741834	MVSTBR 2,5/ 4-ST-5,08 BK
5450984	BCVP-508R- 4 GN	1792265	MVSTBR 2,5/ 4-ST-5,08
5438197	BCVP-508R- 4 GY	1764060	MVSTBR 2,5/ 4-ST-5,08 GY
5452754	BCVP-508R- 5 BK	1741821	MVSTBR 2,5/ 5-ST-5,08 BK
5450997	BCVP-508R- 5 GN	1792278	MVSTBR 2,5/ 5-ST-5,08
5452755	BCVP-508R- 6 BK	1736506	MVSTBR 2,5/ 6-ST-5,08 BK
5451006	BCVP-508R- 6 GN	1792281	MVSTBR 2,5/ 6-ST-5,08
5451019	BCVP-508R- 7 GN	1792294	MVSTBR 2,5/ 7-ST-5,08
5452757	BCVP-508R- 8 BK	1777701	MVSTBR 2,5/ 8-ST-5,08 BK
5451022	BCVP-508R- 8 GN	1792304	MVSTBR 2,5/ 8-ST-5,08
5451035	BCVP-508R- 9 GN	1792317	MVSTBR 2,5/ 9-ST-5,08



## Product Discontinuation

5438249	BCVP-508R- 9 GY		
5451048	BCVP-508R-10 GN	1792320	MVSTBR 2,5/10-ST-5,08
5451051	BCVP-508R-11 GN	1792333	MVSTBR 2,5/11-ST-5,08
5451064	BCVP-508R-12 GN	1792346	MVSTBR 2,5/12-ST-5,08
5438278	BCVP-508R-12 GY		
5451077	BCVP-508R-13 GN	1792359	MVSTBR 2,5/13-ST-5,08
5438294	BCVP-508R-14 GY		
5451093	BCVP-508R-15 GN	1792375	MVSTBR 2,5/15-ST-5,08
5451103	BCVP-508R-16 GN	1792388	MVSTBR 2,5/16-ST-5,08
5438317	BCVP-508R-16 GY		
5451116	BCVP-508R-17 GN	1792391	MVSTBR 2,5/17-ST-5,08
5451129	BCVP-508R-18 GN	1792401	MVSTBR 2,5/18-ST-5,08
5438359	BCVP-508R-20 GY		
5438977	BCVP-508RF- 2 GY	1716009	MVSTBR 2,5/ 2-STF-5,08 GY
5451200	BCVP-508RF- 3 GN	1835106	MVSTBR 2,5/ 3-STF-5,08
5438980	BCVP-508RF- 3 GY	1920590	MVSTBR 2,5/ 3-STF-5,08 GY
5438993	BCVP-508RF- 4 GY		
5451226	BCVP-508RF- 5 GN	1835122	MVSTBR 2,5/ 5-STF-5,08
5451239	BCVP-508RF- 6 GN	1835135	MVSTBR 2,5/ 6-STF-5,08
5439015	BCVP-508RF- 6 GY		
5451242	BCVP-508RF- 7 GN	1835148	MVSTBR 2,5/ 7-STF-5,08
5439028	BCVP-508RF- 7 GY		
5452829	BCVP-508RF- 8 BK	1848011	MVSTBR 2,5/ 8-STF-5,08 BK
5451255	BCVP-508RF- 8 GN	1835151	MVSTBR 2,5/ 8-STF-5,08
5451268	BCVP-508RF- 9 GN	1835164	MVSTBR 2,5/ 9-STF-5,08
5439044	BCVP-508RF- 9 GY		
5451271	BCVP-508RF-10 GN	1835177	MVSTBR 2,5/10-STF-5,08
5439057	BCVP-508RF-10 GY		
5451284	BCVP-508RF-11 GN	1835180	MVSTBR 2,5/11-STF-5,08
5439060	BCVP-508RF-11 GY		
5452833	BCVP-508RF-12 BK	1921832	MVSTBR 2,5/12-STF-5,08 BK
5439073	BCVP-508RF-12 GY		
5452834	BCVP-508RF-13 BK		
5451307	BCVP-508RF-13 GN	1835203	MVSTBR 2,5/13-STF-5,08
5451310	BCVP-508RF-14 GN	1835216	MVSTBR 2,5/14-STF-5,08
5451323	BCVP-508RF-15 GN	1835229	MVSTBR 2,5/15-STF-5,08
5439109	BCVP-508RF-15 GY		
5451336	BCVP-508RF-16 GN	1835232	MVSTBR 2,5/16-STF-5,08
5452880	BCVP-508W- 2 BK	1783287	MVSTBW 2,5/ 2-ST-5,08 BK
5455963	BCVP-508W- 2 BK BDWH:-GND		
5455976	BCVP-508W- 2 BK BDWH:IN		
5451381	BCVP-508W- 2 GN	1792757	MVSTBW 2,5/ 2-ST-5,08
5454948	BCVP-508W- 2 GN BD:NZ		
5439772	BCVP-508W- 2 GY	1783889	MVSTBW 2,5/ 2-ST-5,08 GY
5454935	BCVP-508W- 2 GY BD:NZ		
5452881	BCVP-508W- 3 BK	1836914	MVSTBW 2,5/ 3-ST-5,08 BK
5454964	BCVP-508W- 3 BK BDWH:-NO		
5451394	BCVP-508W- 3 GN	1792760	MVSTBW 2,5/ 3-ST-5,08
5439785	BCVP-508W- 3 GY	1783685	MVSTBW 2,5/ 3-ST-5,08 GY
5474216	BCVP-508W- 3 GY BD:-NO		
5452882	BCVP-508W- 4 BK	1836901	MVSTBW 2,5/ 4-ST-5,08 BK



## Product Discontinuation

5451404	BCVP-508W- 4 GN	1792773	MVSTBW 2,5/ 4-ST-5,08
5439798	BCVP-508W- 4 GY	1806533	MVSTBW 2,5/ 4-ST-5,08 GY
5451417	BCVP-508W- 5 GN	1792786	MVSTBW 2,5/ 5-ST-5,08
5452884	BCVP-508W- 6 BK	1838268	MVSTBW 2,5/ 6-ST-5,08 BK
5451420	BCVP-508W- 6 GN	1792799	MVSTBW 2,5/ 6-ST-5,08
5439811	BCVP-508W- 6 GY		
5452885	BCVP-508W- 7 BK		
5454980	BCVP-508W- 7 BK BDWH:NZ		
5451433	BCVP-508W- 7 GN	1792809	MVSTBW 2,5/ 7-ST-5,08
5439824	BCVP-508W- 7 GY		
5452886	BCVP-508W- 8 BK	1738957	MVSTBW 2,5/ 8-ST-5,08 BK
5451446	BCVP-508W- 8 GN	1792812	MVSTBW 2,5/ 8-ST-5,08
5439837	BCVP-508W- 8 GY	1829293	MVSTBW 2,5/ 8-ST-5,08 GY
5451459	BCVP-508W- 9 GN	1792825	MVSTBW 2,5/ 9-ST-5,08
5451462	BCVP-508W-10 GN	1792838	MVSTBW 2,5/10-ST-5,08
5439866	BCVP-508W-11 GY		
5451488	BCVP-508W-12 GN	1792854	MVSTBW 2,5/12-ST-5,08
5451491	BCVP-508W-13 GN	1792867	MVSTBW 2,5/13-ST-5,08
5439882	BCVP-508W-13 GY		
5451501	BCVP-508W-14 GN	1792870	MVSTBW 2,5/14-ST-5,08
5451514	BCVP-508W-15 GN	1792883	MVSTBW 2,5/15-ST-5,08
5439905	BCVP-508W-15 GY		
5451527	BCVP-508W-16 GN	1792896	MVSTBW 2,5/16-ST-5,08
5439918	BCVP-508W-16 GY		
5451569	BCVP-508W-20 GN	1792935	MVSTBW 2,5/20-ST-5,08
5439950	BCVP-508W-20 GY		
5451611	BCVP-508WF- 2 GN	1834903	MVSTBW 2,5/ 2-STF-5,08
5451624	BCVP-508WF- 3 GN	1834916	MVSTBW 2,5/ 3-STF-5,08
5440596	BCVP-508WF- 4 GY		
5451640	BCVP-508WF- 5 GN	1834932	MVSTBW 2,5/ 5-STF-5,08
5440606	BCVP-508WF- 5 GY		
5451653	BCVP-508WF- 6 GN	1834945	MVSTBW 2,5/ 6-STF-5,08
5440619	BCVP-508WF- 6 GY		
5452957	BCVP-508WF- 7 BK	1763782	MVSTBW 2,5/ 7-STF-5,08 BK
5440622	BCVP-508WF- 7 GY		
5452958	BCVP-508WF- 8 BK		
5451679	BCVP-508WF- 8 GN	1834961	MVSTBW 2,5/ 8-STF-5,08
5451682	BCVP-508WF- 9 GN	1834974	MVSTBW 2,5/ 9-STF-5,08
5440648	BCVP-508WF- 9 GY		
5451695	BCVP-508WF-10 GN	1834987	MVSTBW 2,5/10-STF-5,08
5440651	BCVP-508WF-10 GY		
5451718	BCVP-508WF-12 GN	1835009	MVSTBW 2,5/12-STF-5,08
5440677	BCVP-508WF-12 GY		
5452963	BCVP-508WF-13 BK		