



PE-3 297X420±2MM

修正 REVISIONS	08/08/14
A1 CHECK & ISSUE	

**說明 GENERAL NOTES**

1. DIMENSIONS MARKED WITH "\*" INDICATE CRITICAL DIMENSIONS WHICH NEED TO BE INSPECTED IN EVERY LOT MUST EXCEED 1.33 FOR CRITICAL DIMENSIONS. EDGE MUST BE THE STEP OF CASE WHEN ASSEMBLED.

長度區分	容許公差區分 (MM)			
規格	A	B	C	D
低於 8 LESS THAN 8	±0.05	±0.1	±0.2	±0.4
8-20 8-20	±0.05	±0.1	±0.2	±0.4
20-30 20-30	±0.05	±0.1	±0.2	±0.4
30-40 30-40	±0.05	±0.1	±0.2	±0.4
40-50 40-50	±0.05	±0.1	±0.2	±0.4
50-60 50-60	±0.05	±0.1	±0.2	±0.4
60-70 60-70	±0.05	±0.1	±0.2	±0.4
70-80 70-80	±0.05	±0.1	±0.2	±0.4
80-90 80-90	±0.05	±0.1	±0.2	±0.4
90-100 90-100	±0.05	±0.1	±0.2	±0.4

核准 APPROVED	
審核 CHECKED	
安規 SAFETY	
設計 DESIGN	SAI Z 08/05/14
製圖 DRAWN	
THIRD ANGLE PROJECTION	
公差 TOLERANCE	B
比例 SCALE	1:1
單位 UNIT	MM
機型 MODEL	PSA10F-050(P)-R
處理 TREATMENT	
材料 MATERIAL	
名稱 DESCRIPTION	OUTLINE DRAWING
製圖 PART NO.	PES06510-A1