

# Change Notice S, ST, LW, SW, SB & SDB Series

## Change to Method of Identification for S & ST Toggles, LW & SW Rockers, SB & SDB Pushbuttons

Type of Change:

- Engineering     Part Number  
 Product         Appearance

The process by which a switch is identified on the switch case will be changing. Previously, identification had been printed on the case, but the method will be revised to application of a label. The logo will be also be updated on the label. These changes will effect both standard and custom products for the S and ST Toggles, LW and SW Rockers, SB and SDB Pushbuttons. The table below lists the standard part numbers that will be effected by this change.

Before Change	After Change
Printing	Label

Part Nos. Effected by the Change to Identification Labels					
S1A	S3AW	S7B	S31F	S42F	S332F
S1AL	S3B	S8AW	S32	S43	S332T
S1AW	S3F	S9AW	S32F	S43F	S333
S1B	S5AW	S21A	S33	S45	S333F
S1F	S6A	S21AL	S33F	S48	S333T
S2A	S6AL	S21AW	S35	S49	S335
S2AL	S6AW	S21B	S38	S114	S335T
S2AW	S6B	S25AW	S39	S116	S338
S2B	S7A	S28AW	S41	S331	S338T
S2F	S7AL	S29AW	S41F	S331F	S339
S3A	S7AW	S31	S42	S332	S339T
S3AL					
ST40AM110	ST40DM110	ST40EM110	ST50AM220	ST50DM220	ST50EM220
LW3021A					
SW3001A	SW3002A	SW3003A	SW3006A	SW3007A	SW3008A
SB25	SB61A	SB61B	SB63A		
SDB222F	SDB222M	SDB222S			

### Notes

There may be a mix of previous and updated methods of identification on switches until the transition is complete. Visit NKK Switches' website or contact the factory if more information is needed.

### Effective Date

Changes to method of identification on switch cases will be effective March 2015.















**NKK SWITCHES**

<http://www.nkkswitches.com> • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

# Change Notice

## S, ST, LW, SW, SB & SDB Series

Part Number	Before Change	After Change
S1A S1B S2A S2B		
S1AL S2AL		
S1AW S2AW S5AW		
S3A S3B		
S3AL		
S3AW S8AW S9AW		



7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

<http://www.nkkswitches.com> • 1.877.2BUYNKK (228.9655)

# Change Notice

## S, ST, LW, SW, SB & SDB Series

Part Number	Before Change	After Change
S6A S6B S21A S21B		
S6AL S21AL		
S6AW S21AW		
S7A S7B		
S7AL		
S7AW		

















7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

<http://www.nkkswitches.com> • 1.877.2BUYNKK (228.9655)

# Change Notice

## S, ST, LW, SW, SB & SDB Series

Part Number	Before Change	After Change
S1F S2F SW3001A SW3002A		
S3F SW3003A		
S25AW S28AW S29AW		
S31 S32 S35		
S33 S38 S39		
S31F S32F		
S33F		



7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

<http://www.nkkswitches.com> • 1.877.2BUYNKK (228.9655)

# Change Notice

## S, ST, LW, SW, SB & SDB Series

Part Number	Before Change	After Change
S41 S42 S45		
S43 S48 S49		
S41F S42F		
S43F		
S114 S116		
S331 S332 S335		
S333 S338 S339		



7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

<http://www.nkkswitches.com> • 1.877.2BUYNKK (228.9655)

# Change Notice

## S, ST, LW, SW, SB & SDB Series

Part Number	Before Change	After Change
S331F S332F		
S332T S333T		
S333F S335T S338T S339T		
ST40AM110 ST40DM110 ST40EM110		
ST50AM220 ST50DM220 ST50EM220		
LW3021A		















7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

<http://www.nkkswitches.com> • 1.877.2BUYNKK (228.9655)

# Change Notice

## S, ST, LW, SW, SB & SDB Series

Part Number	Before Change	After Change
SW3006A		
SW3007A SW3008A		
SB25		
SB61A SB61B		
SB63A		
SDB222S SDB222F SDB222M		



7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

<http://www.nkkswitches.com> • 1.877.2BUYNKK (228.9655)