



Product Termination Notification

October 23rd, 2017

Product Change Notification #: 2017030T Rev 1

Subject: Lumileds announces product termination for LUXEON S2000,S3000,S5000

Overview

Lumileds is announcing the discontinuation of the LUXEON S2000, S3000 and S5000 part numbers in Attachment A. At this time, Lumileds is ready to proceed with the end of life for this product. The details and supporting documents are attached below.

Description of Change(s):	LUXEON S2000, S3000 and S5000 end of life
Customer Impact and Recommended Actions:	- discontinuation of product life
Products affected:	LUXEON S2000, S3000 and S5000
Reference Documents/Attachments:	Attachment A: Affected Part Numbers
Customer part number(s), if applicable:	- See Attachment A for Affected Lumileds part numbers
Last order date, if necessary, of obsolesced product	March 31 st , 2018
Last ship date, if necessary, of obsolesced product	September 30 th 2018

Please considering these replacement products:

- [LUXEON CoB Core Range](#)
- [LUXEON CoB Core Range – High Density](#)
- [Matrix Platform light engines](#)

Next Steps

As a next step, please provide acknowledgement of receipt of this PTN and provide feedback along with any additional requests to your Lumileds Account Manager or Quality Manager no later than **(December 31st, 2017)**.

Contact:

If you have any questions, or need any further assistance, please contact your Lumileds sales representative.

CONFIDENTIAL

Document No. 30574135

Rev. AB



Attachments

Attachment A: Affected part numbers

LXS0-PR00-0017
LXS0-PR00-0017N
LXS0-PR00-0024
LXS0-PR00-0024N
LXS0-PR00-0041
LXS0-PR00-0041N
LXS7-PW40-0017
LXS7-PW40-0017N
LXS7-PW40-0024
LXS7-PW40-0024N
LXS7-PW40-0041
LXS7-PW40-0041N
LXS7-PW50-0017
LXS7-PW50-0017N
LXS7-PW50-0024
LXS7-PW50-0024N
LXS7-PW50-0041
LXS7-PW50-0041N
LXS7-PW57-0017
LXS7-PW57-0017N
LXS7-PW57-0024
LXS7-PW57-0024N
LXS7-PW57-0041
LXS7-PW57-0041N
LXS8-E30-0012
LXS8-PW27-0017
LXS8-PW27-0017N
LXS8-PW27-0024
LXS8-PW27-0024N
LXS8-PW27-0041
LXS8-PW27-0041N
LXS8-PW30-0017
LXS8-PW30-0017N
LXS8-PW30-0024
LXS8-PW30-0024N
LXS8-PW30-0041

CONFIDENTIAL
Document No. 30574135
Rev. AB



Attachment A Affected Parts continued:

LXS8-PW30-0041N
LXS8-PW35-0017
LXS8-PW35-0017N
LXS8-PW35-0024
LXS8-PW35-0024N
LXS8-PW35-0041
LXS8-PW35-0041N
LXS8-PW40-0017
LXS8-PW40-0017N
LXS8-PW40-0024
LXS8-PW40-0024N
LXS8-PW40-0041
LXS8-PW40-0041N
LXS8-PW50-0017
LXS8-PW50-0017N
LXS8-PW50-0024
LXS8-PW50-0024N
LXS8-PW50-0041
LXS8-PW50-0041N
LXS9-E30-0012
LXS9-PW27-0017
LXS9-PW27-0017N
LXS9-PW27-0024
LXS9-PW27-0024N
LXS9-PW27-0041
LXS9-PW27-0041N
LXS9-PW30-0017
LXS9-PW30-0017N
LXS9-PW30-0024
LXS9-PW30-0024N
LXS9-PW30-0041
LXS9-PW30-0041N
L2SK-4080007CSQ001

CONFIDENTIAL
Document No. 30574135
Rev. AB



Blank Page